

AGENDA Consents & Regulatory

Tuesday 13 October 2020, 9.30am



Consents and Regulatory Committee

13 October 2020 09:30 AM - 10:30 AM

| Ager | nda Topic | Page |
|--------|---|------|
| Openir | ng Karakia | 4 |
| • | gies ogy was received from Councillor M G Davey. ation of Late Items | |
| 1. | Confirmation of Minutes - 1 September 2020 | 5 |
| 2. | Resource consents issued under delegated authority and applications in progress | 11 |
| 3. | Consent Monitoring Annual Reports | 30 |
| 4. | Incident, Compliance Monitoring Non-compliances and Enforcement Summary | 53 |
| 5. | Public Excluded Recommendations | 100 |
| 6. | Confirmation of Public Excluded Minutes - 1 September 2020 | 101 |



Purpose of Consents and Regulatory Committee meeting

This committee attends to all matters in relation to resource consents, compliance monitoring and pollution incidents, biosecurity monitoring and enforcement.

Responsibilities

Consider and make decisions on resource consent applications pursuant to the *Resource Management Act* 1991.

Ensure adequate compliance monitoring of resource use consents and receive decisions on enforcement actions in the event of non-compliance, pursuant to the *Resource Management Act* 1991.

Consider and make decisions on monitoring and enforcement matters associated with plant and animal pest management.

Other matters related to the above responsibilities.

Membership of Consents and Regulatory Committee

| Councillor D L Lean (Chairperson) | Councillor C S Williamson (Deputy Chairperson) |
|-----------------------------------|--|
| Councillor M J Cloke | Councillor M G Davey |
| Councillor C L Littlewood | Councillor D H McIntyre |
| Councillor E D Van Der Leden | Councillor D N MacLeod (ex officio) |
| Councillor M P Joyce (ex officio) | |

Representative Members

Ms E Bailey Mr K Holswich Mr M Ritai

Health and Safety Message

Emergency Procedure

In the event of an emergency, please exit through the emergency door in the committee room by the kitchen.

If you require assistance to exit please see a staff member.

Once you reach the bottom of the stairs make your way to the assembly point at the birdcage. Staff will guide you to an alternative route if necessary.

Earthquake

If there is an earthquake - drop, cover and hold where possible.

Please remain where you are until further instruction is given.



Whakataka te hau

Karakia to open and close meetings

| Whakataka te hau ki te uru | Cease the winds from the west |
|------------------------------|---|
| Whakataka te hau ki tonga | Cease the winds from the south |
| Kia mākinakina ki uta | Let the breeze blow over the land |
| Kia mātaratara ki tai | Let the breeze blow over the ocean |
| Kia hī ake ana te atakura | Let the red-tipped dawn come with a sharpened air |
| He tio, he huka, he hauhu | A touch of frost, a promise of glorious day |
| Tūturu o whiti whakamaua kia | Let there be certainty |
| tina. | Secure it! |
| Tina! | Draw together! Affirm! |
| Hui ē! Tāiki ē! | |



Resolves

That the Consents and Regulatory Committee of the Taranaki Regional Council:

- a) <u>takes as read</u> and <u>confirms</u> the minutes of the Consents and Regulatory Committee Meeting of the Taranaki Regional Council held in the Taranaki Regional Council Chambers, 47 Cloten Road, Stratford on Tuesday 1 September 2020 at 9.30am
- b) <u>notes</u> that the recommendations therein were adopted by the Taranaki Regional Council on Tuesday 22 September 2020.

Matters arising

Appendices/Attachments

Document 2576405: Minutes Consents and Regulatory Committee - 1 September 2020



MINUTES Consents & Regulatory

| Date | 1 September 2020, 9.30am | | |
|-------------------------------|---|---|---|
| Venue: | Taranaki Regional Council chambers, 47 Cloten Road, Stratford | | |
| Document: | 2576405 | | |
| Members | Councillors | D L Lean M J Cloke M G Davey C L Littlewood D H McIntyre | Committee Chairperson <i>via zoom</i> |
| | | E D Van Der Leden C S Williamson | via zoom via zoom |
| | | M P Joyce | ex officio |
| | | D N MacLeod | ex officio |
| Representative Members | Ms | E Bailey K Holswich | Iwi Representative (<i>via zoom</i>) Iwi Representative |
| Attending | Messrs | M J Nield S Ruru | Acting Chief Executive |
| | Ms Ms Miss Mr | G K Bedford A D McLay C McLellan B Pope P Ledingham V McKay K Holland L Davidson P Moeahu | Director - Environment Quality Director - Resource Management Consents Manager Compliance Manager Communications Adviser Science Manager - Chemistry Communications Adviser Communications Adviser |
| | One member Daily News. | of the public and one | member of the Media, Taranaki |
| Opening Karakia | The meeting opened with a group karakia. | | |
| Apologies | Apologies we Lean/MacLe | | ncillor M P Joyce and Mr M Ritai. |
| Notification of Late Items | There were no | o late items. | |

1. Confirmation of Minutes – Tuesday 21 July 2020

Resolved

That the Consents and Regulatory Committee of the Taranaki Regional Council:

- a) <u>takes as read</u> and <u>confirms</u> the minutes of the Consents and Regulatory Committee meeting of the Taranaki Regional Council held in the Taranaki Regional Council chambers, 47 Cloten Road, Stratford on Tuesday 21 July 2020 at 9.30am
- b) <u>notes</u> the recommendations therein were adopted by the Taranaki Regional Council on Tuesday 11 August 2020. Davey/Holswich

Matters arising

It was requested that members are given more time for reading of meeting materials as often the agendas are quite large and the allocated time is not enough. A paper will be brought back to members regarding this.

2. Resource Consents Issued Under Delegated Authority and Applications in Progress

- 2.1 Mr C McLellan, Consents Manager, spoke to the memorandum advising members of consents granted, consents under application and consent processing actions since the last meeting.
- 2.2 The Mana Whakahono a Rohe agreement is back on track. The consenting side of the agreement needs more work. Once the agreement is finalised it will come before the Consents and Regulatory Committee.
- 2.3 Ms E Bailey, recommended that Council provides a summary of each consent application to Iwi to assist in receiving feedback from Iwi, in particular, where an application does not comply with the Iwi Management Plan.

Recommended

That the Taranaki Regional Council:

 a) <u>provides</u> Iwi with a summary of each consent application summarising the application and noting if it does not comply with the Iwi Management Plan. Bailey/Van Der Leden For - 2 Against - 9 Motion lost

Recommended

That the Taranaki Regional Council:

a) <u>receives</u> the schedule of resource consents granted and other consent processing actions made under delegated authority.

Cloke/McIntyre

3. Appointment of Hearing Committee – Remediation NZ Uruti composting Facility Consents

- 3.1 Mr A D McLay, Director Resource Management, spoke to the memorandum to delegate to a Hearing Committee the authority to determine applications by Remediation (NZ) Limited (consents 05838-3.0 & 05839-3.0).
- 3.2 The Taranaki Regional Council currently has only two Elected Members who are accredited to sit on a hearing panel. It was decided at a previous meeting that the Council would start phasing out accreditation of Members.

Recommended

That the Taranaki Regional Council:

- a) <u>receives</u> this memorandum
- b) subject to a hearing being necessary, in accordance with section 34A(1) of the Resource Management Act <u>appoints</u> Cr M Joyce and Cr N Walker as hearing commissioners, and <u>delegates</u> them the power to hear and determine the applications lodged by Remediation (NZ) Limited (consents 05838-3.0 & 05839-3.0)
- c) subject to a hearing being necessary, also <u>appoints</u> an accredited hearing commissioner, with cultural expertise, to the panel, under the same terms as (b) above; who will be appointed by the Acting Chief Executive.

MacLeod/Cloke

4. Consent Monitoring Annual Reports

- 4.1 Mr G K Bedford, Director Environment Quality, introduced Ms V MacKay to speak to the memorandum advising members of 14 tailored compliance monitoring report.
- 4.2 Councillors C L Littlewood and D N MacLeod declared and interest in 20-31 Port Taranaki Ltd Maintenance Dredging Monitoring Programme Biennial Report 2018-2020.

Recommended

That the Taranaki Regional Council:

- a) <u>receives</u> the 20-6 STDC Patea Beach Green Waste Discharge Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- b) <u>receives</u> the 20-13 Waiinu Beach Settlement Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- c) <u>receives</u> the 20-14 Wai-iti Beach Retreat Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- d) <u>receives</u> the 20-18 Todd Energy Aquatic Centre Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- e) <u>receives</u> the 20-19 Urenui and Onaero Beach Camps Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- f) <u>receives</u> the 20-31 Port Taranaki Ltd Maintenance Dredging Monitoring Programme Biennial Report 2018-2020 and <u>adopts</u> the specific recommendations therein

- g) <u>receives</u> the 20-34 Westside Kauri-E Hydraulic Fracturing Monitoring Programme Report 2018-2019 and <u>adopts</u> the specific recommendations therein
- h) <u>receives</u> the 20-35 Greymouth Petroleum Ltd Radnor-B Hydraulic Fracturing Monitoring Programme Report 2018-2019 and <u>adopts</u> the specific recommendations therein
- i) <u>receives</u> the 20-36 Todd Petroleum Ltd Mangahewa-C Hydraulic Fracturing Monitoring Programme Report 2018-2019 and <u>adopts</u> the specific recommendations therein
- j) <u>receives</u> the 20-37 Greymouth Petroleum Mining Group Ltd Kowhai-D Kowhai-5 well Hydraulic Fracturing Monitoring Programme Report 2018-2019 and <u>adopts</u> the specific recommendations therein
- k) <u>receives</u> the 20-47 ANZCO Foods Waitara Ltd Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- receives the 20-49 Taranaki Galvanizers Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- m) <u>receives</u> the 19-50 NPDC Crematorium Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein
- n) <u>receives</u> the 20-54 STDC Coastal Structures Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein. Lean/Davey

5. Incident, Compliance Monitoring Non-compliances and Enforcement Summary – 1 July 2020 to 13 August 2020

- 5.1 Mr B Pope, Compliance Manager, spoke to the memorandum allowing members to consider and receive the summary of the incidents, compliance monitoring non-compliances and enforcement for the period 1 July 2020 to 13 August 2020.
- 5.2 Councillors C L Littlewood and D N MacLeod declared an interest in relation to the Port Taranaki Limited incident.

Recommended

That the Taranaki Regional Council:

- a) <u>receives</u> this memorandum Incident, Compliance Monitoring Non-compliances and Enforcement Summary - 1 July 2020 to 13 August 2020
- b) <u>receives</u> the summary of the incidents, compliance monitoring non-compliances and enforcement for the period from 1 July 2020 to 13 August 2020, <u>notes</u> the action taken by staff acting under delegated authority and <u>adopts</u> the recommendations therein.

Cloke/Holswich

6. Prosecution Sentencing Decision

6.1 Mr A D McLay, Director – Resource Management, spoke to the memorandum updating Members on the prosecution of Mr Phillip Potroz, for a breach of the Regional Fresh Water Plan for Taranaki involving the discharge of silt/sediment onto land and into water, diverting water, and disturbing and reclaiming the bed of an unnamed tributary of the Kahouri Stream in January and February 2019.

6.2 The total cost of the prosecution well exceeded the fine and was a good message to those contemplating non-compliance.

Recommended

That the Taranaki Regional Council:

a) <u>receives</u> this report and notes the successful outcome of the prosecution against Mr Phillip Potroz

Lean/Holswich

7. Public Excluded

In accordance with section 48(1) of the *Local Government Official Information and Meetings Act 1987*, <u>resolves</u> that the public is excluded from the following part of the proceedings of the Consents and Regulatory Committee Meeting on Tuesday 21 July 2020 for the following reason/s:

Item 8 - Confirmation of Public Excluded Minutes - 21 July 2020

THAT the public conduct of the whole or the relevant part of the proceedings of the meeting would be likely to result in the disclosure of information where the withholding of the information is necessary to protect information where the making available of the information would be likely unreasonably to prejudice the commercial position of the person who supplied or who is the subject of the information.

Item 9 - Schedule of Taranaki Regional Council Prosecutions

That the public conduct of the whole or relevant part of the proceedings would be likely to prejudice the maintenance of the law, including the prevention, investigation, and detection of offences, and the right to a fair trial.

Item 10 - Prosecution

That the public conduct of the whole or relevant part of the proceedings would be likely to prejudice the maintenance of the law, including the prevention, investigation, and detection of offences, and the right to a fair trial.

Lean/MacLeod

There being no further business the Committee Chairman, Councillor D L Lean, declared the public meeting of the Consents and Regulatory Committee closed at 10.24am.

Confirmed

Consents and Regulatory Committee Chairperson: _

> D L Lean 13 October 2020



Purpose

1. The purpose of this memorandum is to advise the Council of consents granted, consents under application and of consent processing actions since the last meeting. This information is summarised in attachments at the end of this report.

Executive summary

2. Memorandum to advise the Council of recent consenting actions made under regional plans and the Resource Management Act 1991, in accordance with Council procedures and delegations.

Recommendation

That the Taranaki Regional Council:

a) <u>receives</u> the schedule of resource consents granted and other consent processing actions, made under delegated authority.

Background

3. The attachments show resource consent applications, certificates of compliance and deemed permitted activities that have been investigated and decisions made by officers of the Taranaki Regional Council. They are activities having less than minor adverse effects on the environment, or having minor effects where affected parties have agreed to the activity. In accordance with sections 87BB, 104 to 108 and 139 of the Resource Management Act 1991, and pursuant to delegated authority to make these decisions, the Chief Executive or the Director – Resource Management has allowed the consents, certificates of compliance and deemed permitted activities.

- 4. The exercise of delegations under the Resource Management Act 1991 is reported for Members' information. Under the delegations manual, consent processing actions are to be reported to the Consents and Regulatory Committee.
- 5. In addition to the details of the activity consented, the information provided identifies the Iwi whose rohe (area of interest) the activity is in. If the activity is in an area of overlapping rohe both Iwi are shown. If the activity is within, adjacent to, or directly affecting a statutory acknowledgement (area of special interest), arising from a Treaty settlement process with the Crown, that is also noted.
- 6. Also shown, at the request of Iwi members of the Council, is a summary of the engagement with Iwi and Hapū, undertaken by the applicant and the Council during the application process. Other engagement with third parties to the consent process is also shown. The summary shows the highest level of involvement that occurred with each party. For example, a party may have been consulted by the applicant, provided with a copy of the application by the Council, served notice as an affected party, lodged a submission and ultimately agreed with the consent conditions. In that case the summary would show only 'agreed with consent conditions', otherwise reporting becomes very complicated.
- 7. The attachment titled 'Consent Processing Information' includes the figure 'Consent Applications in Progress' which shows the total number of applications in the consent processing system over the last twelve months. The number of applications for the renewal of resource consents is also shown. The difference between the two is the number of new applications, including applications for a change of consent conditions. New applications take priority over renewal applications. Renewal applications are generally put on hold, with the agreement of the applicant, and processed when staff resources allow. A consent holder can continue to operate under a consent that is subject to renewal. The above approach is pragmatic and ensures there are no regulatory impediments to new activities requiring authorisation.
- 8. The attachment also includes:
 - Applications in progress table the number of applications in progress at the end of each month (broken down into total applications and the number of renewals in progress) for this year and the previous two years.
 - Potential hearings table outlining the status of applications where a hearing is anticipated and the decision maker(s) (e.g. a hearing panel) has been appointed.
 - Consents issued table the number of consents issued at the end of each month for this year and the previous two years.
 - Breakdown of consents issued. This is the number of consents issued broken down by purpose new, renewals, changes or review.
 - Types of consents issued, further broken down into notification types nonnotified, limited notified or public notified.
 - Number of times that the public and iwi were involved in an application process for the year so far.
 - Application processing time extensions compared to the previous years.
 - Consent type process shows the notification type including applications submitted on and the pre-hearing resolution numbers.
 - Applications that have been returned because they are incomplete.

Decision-making considerations

9. Part 6 (Planning, decision-making and accountability) of the *Local Government Act* 2002 has been considered and documented in the preparation of this agenda item. The recommendations made in this item comply with the decision-making obligations of the *Act*.

Financial considerations—LTP/Annual Plan

10. This memorandum and the associated recommendations are consistent with the Council's adopted Long-Term Plan and estimates. Any financial information included in this memorandum has been prepared in accordance with generally accepted accounting practice.

Policy considerations

11. This memorandum and the associated recommendations are consistent with the policy documents and positions adopted by this Council under various legislative frameworks including, but not restricted to, the *Local Government Act* 2002, the *Resource Management Act* 1991 and the *Local Government Official Information and Meetings Act* 1987.

lwi considerations

12. This memorandum and the associated recommendations are consistent with the Council's policy for the development of Māori capacity to contribute to decision-making processes (schedule 10 of the *Local Government Act* 2002) as outlined in the adopted long-term plan and/or annual plan. Similarly, iwi involvement in adopted work programmes has been recognised in the preparation of this memorandum.

Legal considerations

13. This memorandum and the associated recommendations comply with the appropriate statutory requirements imposed upon the Council.

Appendices/Attachments

Document 2603867: List of non-notified consents Document 2603898: Schedule of non-notified consents

Document 2604106: Consents processing charts for Agenda

| Coastal Perm | iit | | | | | |
|---------------------|-------------------------------------|---|------------------------------|--------------------------|----------------------------|------------------|
| Consent | Holder | Subtype | Industry Primary | Industry Secondary | Purpose Primary | Activity Purpose |
| R2/10073-2.0 | Energyworks Limited | Air Discharge - Abrasive Blasting (CMA) | Engineering | | Abrasive Blasting | New |
| Discharge Pe | ermit | | | | | |
| Consent | Holder | Subtype | Industry Primary | Industry Secondary | Purpose Primary | Activity Purpose |
| R2/2202-3 0 | Paul & Robyn Mander | Land - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Replace |
| <u>R2/2225-3 2</u> | William Myers Family Trust | Water - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Change |
| <u>R2/3483-3 0</u> | Michael & Kathryn Edgcombe | Land - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Replace |
| <u>R2/4120-30</u> | Dorville Trusts Partnership | Land - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Replace |
| R2/4937-30 | Brugglen & Messen Trusts | Land - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Replace |
| R2/6358-2 0 | C & A Dairies Limited | Land/Water - Animal Waste | Agriculture | Farming - Dairy | Effluent disposal | Replace |
| R2/7853-1.1 | Greymouth Petroleum Limited | Land - Stormwater | Energy | Wellsite | Exploration and Production | Change |
| R2/9606-2 0 | Energyworks Limited | Air - Abrasive Blasting | Engineering | | Abrasive Blasting | Replace |
| R2/9880-1.1 | Methanex NZ Limited | Water - Stormwater | Energy | Petrochemical Processing | | Change |
| R2/9881-1.1 | Methanex NZ Limited | Water - Stormwater | Energy | Petrochemical Processing | | Change |
| R2/10838-1.0 | Mangati Properties (2001) Limited | Land/Water Industry | Property Development | | Subdivision | New |
| R2/10844-1.0 | Intergroup Limited | Air - Abrasive Blasting | Engineering | | Abrasive Blasting | New |
| R2/10853-1.0 | Todd Energy Limited | Air - Industry | Energy | Wellsite | Exploration and Production | New |
| R2/10854-1.0 | Todd Energy Limited | Air - Industry | Energy | Wellsite | Exploration and Production | New |
| R2/10855-1.0 | Greymouth Petroleum Turangi Limited | Land - Stormwater | Energy | Wellsite | Exploration and Production | New |
| R2/10856-1.0 | Fonterra Limited | Land - Stormwater | Manufacturing and Processing | Dairy Processing | | New |
| Land Use Co | nsent | | | | | |
| Consent | Holder | Subtype | Industry Primary | Industry Secondary | Purpose Primary | Activity Purpose |
| <u>R2/10798-1.1</u> | Peter John Colman | Structure - Culvert | Property Development | | Access | Change |
| R2/10857-1.0 | NZL Forestry Group Limited | Forestry – Earthworks | Forestry | | Forest Harvesting | New |

#2603867-v1

<u>R2/10844-1.0</u>

Intergroup Limited PO Box 58087, Botany, Auckland 2163 Commencement Date: 21 Aug 2020 Expiry Date: 01 Jun 2038 Review Dates: Jun 2023, Jun 2026, Jun 2029, Jun 2032, Jun 2035 Activity Class: Restricted discretionary

Location: 169 De Havilland Drive, Bell Block & **Application Purpose:** New various locations throughout the Taranaki region

To discharge emissions into the air from abrasive blasting operations at a permanent site at De Havilland Drive, Bell Block and from mobile operations throughout the Taranaki region excluding the Coastal Marine Area

Rohe:

Ngaa Rauru Kiitahi (Statutory Acknowledgement) Ngaruahine (Statutory Acknowledgement) Ngati Maru Ngati Mutunga (Statutory Acknowledgement) Ngati Ruanui (Statutory Acknowledgement) Ngati Tama (Statutory Acknowledgement) Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| Kettle Handyman Service Limited | Written approval provided |
|---|--|
| Naki Nitro Indoor Karting | Written approval provided |
| Taranaki Pine | Written approval provided |
| Te Kaahui o Rauru - Legal Entity of Ngaa Rauru Kiitahi | Provided with application |
| Te Kahui o Taranaki Trust | Provided with application |
| Te Korowai O Ngaruahine Trust | Comment on application received |
| | • Do not oppose, subject to conditions |
| Te Kotahitanga o Te Atiawa Trust | Provided with application |
| Te Runanga o Ngati Maru (Taranaki) Trust | Provided with application |
| Te Runanga o Ngati Mutunga | Provided with application |
| Te Runanga O Ngāti Ruanui Trust | Provided with application |
| Te Runanga O Ngati Tama | Provided with application |
| Working for Health Ltd | Written approval provided |

| <u>R2/10798-1.1</u> | Commencement Date: 26 Aug 2020 |
|--|--|
| Peter John Colman | Expiry Date: 01 Jun 2038 |
| 375B Lower Pitone Road, RD 4, New Plymouth 4374 | n Review Dates: Jun 2026, Jun 2032 Activity Class: Discretionary |
| Location: 1788 Mangorei Road, Mangorei | Application Purpose: Change |
| To install a culvert in an unnamed tributary of associated disturbance of the stream bed | the Pukekotahuna Stream, including the |

Change of consent conditions to change the culvert size

Rohe:

Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| Te Kahui o Taranaki Trust | Provided with application |
|----------------------------------|---------------------------------------|
| Te Kotahitanga o Te Atiawa Trust | Comment on application received |
| | • Application lacks sufficient detail |

| <u>R2/10853-1.0</u> | Commencement Date: 31 Aug 2020 |
|--|--|
| Todd Energy Limited | Expiry Date: 01 Jun 2025 |
| PO Box 802, New Plymouth 4340 | Review Dates: Activity Class: Discretionary |
| Location: McKee-D wellsite, 1444 Otaraoa | Application Purpose: New |

Road, Tikorangi

To discharge emissions to air from the plugging and abandonment of three oil and gas wells at the McKee-D wellsite

Rohe:

Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| Otaraua Hapu Trust | Applicant provided application |
|----------------------------------|--------------------------------|
| Te Kotahitanga o Te Atiawa Trust | Provided with application |
| Te Kotahitanga o Te Atiawa Trust | Applicant provided application |

| <u>R2/10854-1.0</u> | Commencement Date: 31 Aug 2020 |
|-------------------------------|--|
| Todd Energy Limited | Expiry Date: 01 Jun 2025 |
| PO Box 802, New Plymouth 4340 | Review Dates: Activity Class: Discretionary |
| | |

Location: McKee-A wellsite, 1444 Otaraoa Road, Tikorangi

Application Purpose: New

To discharge emissions to air from the plugging and abandonment of three oil and gas wells at the McKee-A wellsite

Rohe:

Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

Otaraua Hapu Trust Te Kotahitanga o Te Atiawa Trust Te Kotahitanga o Te Atiawa Trust

R2/10856-1.0

Fonterra Limited PO Box 444, Hawera 4640 Applicant provided application Provided with application Applicant provided application

Commencement Date: 01 Sep 2020 Expiry Date: 01 Jun 2023 **Review Dates:** Activity Class: Controlled

Location: 275 Manawapou Road, Hawera

Application Purpose: New

To discharge stormwater and sediment arising from earthworks into land in the vicinity of an unnamed tributary of the Tangahoe River

Rohe:

Ngati Ruanui

Engagement or consultation:

Te Runanga O Ngāti Ruanui Trust

Provided with application

<u>R2/9606-2.0</u> Energyworks Limited PO Box 346, New Plymouth 4340 Commencement Date: 03 Sep 2020 Expiry Date: 01 Jun 2038 Review Dates: Jun 2023, Jun 2026, Jun 2029, Jun 2032, Jun 2035 Activity Class: Discretionary

Location: 221A Connett Road East, Bell Block & various locations throughout the Taranaki region and the coastal marine area

Application Purpose: Replace

To discharge emissions into the air associated with abrasive blasting operations, spray painting and associated activities at a permanent site at Connett Road East, Bell Block and from mobile operations throughout the Taranaki region, including parts of the coastal marine area

Rohe:

Ngaruahine (Statutory Acknowledgement) Ngati Maru Ngati Mutunga (Statutory Acknowledgement) Ngati Tama (Statutory Acknowledgement) Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

Port Taranaki Limited Te Kahui o Taranaki Trust Te Korowai O Ngaruahine Trust

Te Kotahitanga o Te Atiawa Trust Te Runanga o Ngati Maru (Taranaki) Trust Te Runanga o Ngati Mutunga Te Runanga O Ngati Tama Applicant provided application Provided with application Comment on application received

- Application lacks sufficient detail
- Do not oppose, subject to conditions

Provided with application Provided with application Provided with application Provided with application

| <u>R2/10073-2.0</u> |
|-------------------------------|
| Energyworks Limited |
| PO Box 346, New Plymouth 4340 |

Commencement Date: 03 Sep 2020 Expiry Date: 01 Jun 2038 Review Dates: Jun 2023, Jun 2026, Jun 2029, Jun 2032, Jun 2035 Activity Class: Discretionary

Location: 221A Connett Road East, Bell Block & various locations throughout the Taranaki region and the coastal marine area

Application Purpose: New

To discharge emissions into the air associated with abrasive blasting operations, spray painting and associated activities at a permanent site at Connett Road East, Bell Block and from mobile operations throughout the Taranaki region, including parts of the coastal marine area

Rohe:

Ngaruahine (Statutory Acknowledgement) Ngati Maru Ngati Mutunga (Statutory Acknowledgement) Ngati Tama (Statutory Acknowledgement) Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

Port Taranaki Limited Te Kahui o Taranaki Trust Te Korowai O Ngaruahine Trust

Te Kotahitanga o Te Atiawa Trust Te Runanga o Ngati Maru (Taranaki) Trust Te Runanga o Ngati Mutunga Te Runanga O Ngati Tama Applicant provided application Provided with application Comment on application received

- Application lacks sufficient detail
- Do not oppose, subject to conditions

Provided with application Provided with application Provided with application Provided with application

| 0 | |
|---|--|
| <u>R2/4937-3.0</u> | Commencement Date: 03 Sep 2020 |
| Brugglen & Messen Trusts | Expiry Date: 01 Dec 2041 |
| P & M Ruchti, 104 Wakeman Road, Acacia Bay, Taupo 3330 | Review Dates: Jun 2023, Jun 2029, Jun 2035 Activity Class: Controlled |
| Location: 93B Climie Road, Ngaere | Application Purpose: Replace |
| To discharge farm dairy effluent onto land | |
| Rohe: | |
| Ngaruahine (Statutory Acknowledgement) | |
| Ngati Ruanui | |
| Engagement or consultation: | |
| Te Korowai O Ngaruahine Trust | Comment on application received |
| | • Do not oppose, subject to conditions |
| <u>R2/7853-1.1</u> | Commencement Date: 08 Sep 2020 |
| Greymouth Petroleum Limited | Expiry Date: 01 Jun 2027 |
| PO Box 3394, New Plymouth 4341 | Review Dates: Jun 2021 |
| | Activity Class: Discretionary |
| Location: Turangi-B wellsite, 42 Turangi Road Upper, Motunui (Property owner: RJ Topless) | Application Purpose: Change |
| To discharge treated stormwater from hydroca at the Turangi-B wellsite onto and into land | rbon exploration and production operations |
| Change of consent conditions to increase the ca the allowable chloride concentration of the dise | • |
| Rohe: | |
| Te Atiawa (Statutory Acknowledgement) | |
| Engagement or consultation: | |
| | Consulted by applicant |
| Ngati Rahiri Hapu Trust | Consulted by applicant |
| Ngati Rahiri Hapu Trust Ralston John Topless | Written approval provided |

| <u>R2/10855-1.0</u> | Commencement Date: 08 Sep 2020 |
|--|---|
| Greymouth Petroleum Turangi Limited | Expiry Date: 01 Jun 2025 |
| PO Box 3394, Fitzroy, New Plymouth 4341 | Review Dates: Activity Class: Controlled |
| Location: Turangi-B wellsite, 42 Turangi Road Upper, Motunui (Property owner: R Topless) | Application Purpose: New |
| To discharge stormwater and sediment arising onto and into land | from earthworks at the Turangi-B wellsite |

Rohe:

Te Atiawa (Statutory Acknowledgement)

| Consulted by applicant |
|---------------------------|
| Written approval provided |
| Provided with application |
| |

<u>R2/4120-3.0</u>

Dorville Trusts Partnership Neville & Doreen Sharpe, 587 Taikatu Road, RD 28, Hawera 4678

Location: 587 Taikatu Road, Auroa To discharge farm dairy effluent onto land

Rohe:

Ngaruahine (Statutory Acknowledgement)

Engagement or consultation:

Te Korowai O Ngaruahine Trust

Commencement Date: 11 Sep 2020

Expiry Date: 01 Dec 2048 Review Dates: Jun 2024, Jun 2030, Jun 2036, Jun 2042 Activity Class: Controlled Application Purpose: Replace

Comment on application received

• Do not oppose, subject to conditions

| R2/10857-1.0 NZL Forestry Group Limited | Commencement Date: 15 Sep 2020 Expiry Date: 01 Jun 2023 Review Dates: |
|--|--|
| PO Box 148, Dannevirke 4942 | Activity Class: Restricted discretionary |
| Location: 237B Taumatatahu Road, Ngamatapouri | Application Purpose: New |
| To undertake earthworks relating to harvesting | a plantation forestry |
| Rohe: | |
| Ngaa Rauru Kiitahi | |
| Engagement or consultation: | |
| Te Kaahui o Rauru - Legal Entity of Ngaa Rauru Kiitahi | Provided with application |
| | |
| <u>R2/2202-3.0</u> | Commencement Date: 16 Sep 2020 |
| <u>R2/2202-3.0</u> Paul & Robyn Mander | Commencement Date: 16 Sep 2020 Expiry Date: 01 Dec 2044 |
| | |
| Paul & Robyn Mander | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 Location: 94 Ackworth Road, Lepperton | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 Location: 94 Ackworth Road, Lepperton To discharge farm dairy effluent onto land | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 Location: 94 Ackworth Road, Lepperton To discharge farm dairy effluent onto land Rohe: | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 Location: 94 Ackworth Road, Lepperton To discharge farm dairy effluent onto land Rohe: Te Atiawa (Statutory Acknowledgement) | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled |
| Paul & Robyn Mander 94 Ackworth Road, RD 3, New Plymouth 4373 Location: 94 Ackworth Road, Lepperton To discharge farm dairy effluent onto land Rohe: Te Atiawa (Statutory Acknowledgement) Engagement or consultation: | Expiry Date: 01 Dec 2044 Review Dates: Jun 2026, Jun 2032, Jun 2038 Activity Class: Controlled Application Purpose: Replace |

| <u>R2/9880-1.1</u> | Commencement Date: 16 Sep 2020 |
|-------------------------------------|---|
| Methanex NZ Limited | Expiry Date: 01 Jun 2032 |
| Private Bag 2011, New Plymouth 4342 | Review Dates: Jun 2026 Activity Class: Discretionary |

Location: Omata Tank Farm 2, Centennial Drive, New Plymouth

Activity Class: Discretionary Application Purpose: Change

To discharge stormwater from a methanol storage facility at the Omata tank farm 2 into the Herekawe Stream

Change of consent conditions to allow increase in chloride limit of discharge

Rohe:

Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| Te Kahui o Taranaki Trust | Provided with application |
|----------------------------------|---------------------------|
| Te Kotahitanga o Te Atiawa Trust | Provided with application |

| <u>R2/9881-1.1</u> | Commencement Date: 16 Sep 2020 |
|--|---|
| Methanex NZ Limited | Expiry Date: 01 Jun 2032 |
| Private Bag 2011, New Plymouth 4342 | Review Dates: Jun 2026 Activity Class: Discretionary |
| Location: Omata Tank Farm 1, Centennial Drive, New Plymouth | Application Purpose: Change |

To discharge stormwater from a methanol storage facility at the Omata tank farm 1 into the Herekawe Stream

Change of consent conditions to allow increase in chloride limit of discharge

Rohe:

Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| Te Kahui o Taranaki Trust | Provided with application |
|----------------------------------|---------------------------|
| Te Kotahitanga o Te Atiawa Trust | Provided with application |

| <u>R2/3483-3.0</u> | Commencement Date: 18 Sep 2020 |
|--|--|
| Michael & Kathryn Edgcombe | Expiry Date: 01 Dec 2045 |
| 320 Mana Road, RD 10, Inglewood 4390 | Review Dates: Jun 2027, Jun 2033, Jun 2039 Activity Class: Controlled |
| Location: 320 Mana Road, Ratapiko | Application Purpose: Replace |
| To discharge farm dairy effluent onto land | |

Rohe:

Ngati Maru

| <u>R2/6358-2.0</u> | Commencement Date: 18 Sep 2020 |
|--|--|
| C & A Dairies Limited | Expiry Date: 01 Dec 2026 |
| P K Knowles, 2138 Egmont Road, RD 6, Inglewood 4386 | Review Dates: Jun 2022, Jun 2024 Activity Class: Controlled |
| Location: 2138 Egmont Road, Kaimiro | Application Purpose: Replace |

To discharge farm dairy effluent onto land and after treatment in an oxidation pond system into an unnamed tributary of the Waiwhakaiho River if the land disposal area is unsuitable for effluent disposal

Rohe:

Taranaki (Statutory Acknowledgement) Te Atiawa (Statutory Acknowledgement)

Engagement or consultation:

| New Plymouth District Council | Provided with application |
|----------------------------------|---------------------------|
| Te Kahui o Taranaki Trust | Provided with application |
| Te Kotahitanga o Te Atiawa Trust | Provided with application |

24

| <u>R2/10838-1.0</u> | Commencement Date: 23 Sep 2020 |
|--|--|
| Mangati Properties (2001) Limited | Expiry Date: 01 Jun 2025 |
| 20 Nadine Stanton Drive, Bell Block 4312 | Review Dates: Activity Class: Controlled |
| Location: 3 James Drive, Bell Block | Application Purpose: New |
| To discharge stormwater and sediment arising from earthworks onto and into land and into the Waihowaka Stream | |
| Rohe: | |
| Te Atiawa (Statutory Acknowledgement) | |
| Engagement or consultation: | |
| | Provided with application |
| Te Kotahitanga o Te Atiawa Trust | Provided with application |
| | |
| <u>R2/2225-3.2</u> | Commencement Date: 23 Sep 2020 |
| <u>R2/2225-3.2</u> William Myers Family Trust | Commencement Date: 23 Sep 2020 Expiry Date: 01 Dec 2042 |
| | 1 |
| William Myers Family Trust | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 Location: 485 Taikatu Road, Auroa To discharge farm dairy effluent onto land, a | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an butary of the Rawa Stream |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 Location: 485 Taikatu Road, Auroa To discharge farm dairy effluent onto land, a oxidation pond system, into an unnamed tril | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an butary of the Rawa Stream |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 Location: 485 Taikatu Road, Auroa To discharge farm dairy effluent onto land, a oxidation pond system, into an unnamed tril Change of conditions to change the date for I | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an butary of the Rawa Stream |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 Location: 485 Taikatu Road, Auroa To discharge farm dairy effluent onto land, a oxidation pond system, into an unnamed tril Change of conditions to change the date for I Rohe: Ngaruahine (Statutory Acknowledgement) | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an butary of the Rawa Stream |
| William Myers Family Trust 485 Taikatu Road, RD 28, Hawera 4678 Location: 485 Taikatu Road, Auroa To discharge farm dairy effluent onto land, a oxidation pond system, into an unnamed tril Change of conditions to change the date for I Rohe: | Expiry Date: 01 Dec 2042 Review Dates: Jun 2024, Jun 2030, Jun 2036 Activity Class: Discretionary Application Purpose: Change and until 1 June 2021 after treatment in an butary of the Rawa Stream |

• General opposition

Consents and Regulatory Committee - Resource consents issued under delegated authority and applications in progress

Consent Processing Information



1) Applications in progress

2) Month Ending

| | Ju | ly | Au | g | Se | pt | 0 | ct | No | v | De | ic. | Ja | n | Fe | b | M | ar | Ap | or | Ma | y | Ji | JN. |
|-----------|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|
| | Total | R |
| 2020/2021 | 196 | 157 | 187 | 157 | 221 | 182 | | | | | | | | | | | | | | | | | | |
| 2019/2020 | 136 | 107 | 126 | 101 | 136 | 103 | 129 | 101 | 130 | 101 | 136 | 103 | 135 | 100 | 152 | 130 | 139 | 119 | 142 | 119 | 165 | 136 | 205 | 160 |
| 2018/2019 | 144 | 53 | 124 | 44 | 127 | 43 | 143 | 43 | 142 | 45 | 91 | 58 | 94 | 61 | 98 | 73 | 107 | 70 | 105 | 69 | 105 | 67 | 129 | 92 |

3) Potential Hearings

| Applicant | Description | Notification date | Status | Date Issued |
|-----------|-------------|----------------------|--------|-------------|
| Nil | | | | |

Doc#2604106-v1

| | July | Aug | Sept | Oct | Nov | Dec | Jan | Feb | Mar | April | May | June |
|-----------|------|-----|------|-----|-----|-----|-----|-----|-----|-------|-----|------|
| 2020-2021 | 20 | 38 | 53 | | | | | | | | | |
| 2019-2020 | 26 | 51 | 72 | 102 | 148 | 162 | 188 | 218 | 239 | 245 | 248 | 263 |
| 2018-2019 | 32 | 55 | 66 | 84 | 109 | 186 | 195 | 211 | 225 | 242 | 265 | 286 |

4) Consents Issued (running totals)

5) Breakdown of consents issued

| | New | Renewal | Change | Review | Totals |
|----------------------------|-----|---------|--------|--------|--------|
| 2020-2021 to end September | 13 | 19 | 10 | 11 | 53 |
| 2019-2020 Total | 81 | 138 | 44 | 0 | 263 |
| 2018-2019 Total | 148 | 93 | 45 | 0 | 286 |

6) Types of consents issued - year to date comparison

| | Agricultural | Centra/Local Government | Energy | Forestry | Other | Tot: public notifi | ally | Agricultural | Centra/Local Government | Energy | Forestry | Other | Total Li Notif | | Agricultural | Centra/Local Govern ment | Energy | Forestry | Other | Total N notifie | 202 | Grand Total |
|----------------------------|--------------|----------------------------|--------|----------|-------|--------------------------|------|--------------|----------------------------|--------|----------|-------|-------------------|---|--------------|-----------------------------|---------|----------|-------|--------------------|-----|-------------|
| | | Public | ally N | otified | | % | | | 1 | imited | 1 | | % | | | Nor | n Notif | ied | | % | | |
| July 2018 to June 2019 | 0 | 57 | 0 | 0 | 0 | 19.9% | 57 | 6 | 2 | 0 | 0 | 1 | 3.1% | 9 | 103 | 32 | 41 | 10 | 34 | 76.9% | 220 | 286 |
| July 2019 to June 2020 | 0 | 1 | 0 | 0 | 0 | 0.4% | 1 | 1 | 4 | 0 | 0 | 2 | 2.7% | 7 | 147 | 30 | 28 | 8 | 42 | 97.0% | 255 | 263 |
| July 2020 to end September | 0 | 0 | 0 | 0 | 0 | 0.0% | 0 | 0 | 0 | 0 | 0 | 0 | 0.0% | 0 | 11 | 6 | 16 | 1 | 19 | 100.0% | 53 | 53 |

7) Involvement with third parties for applications granted year to date

| | Consultation/ Involved (number of parties) | Number of Affected Party Approvals (written) | Totals |
|--|--|--|--------|
| District Councils | | | 0 |
| DOC | | | 0 |
| Environmental/Recreational Groups | | | 0 |
| Fish & Game | | | 0 |
| Individuals/Neighbours/Landowners | 0 | 7 | 7 |
| Network Utilities | | | 0 |
| Non Govt Organisations | 2 | 0 | 2 |
| Other Govt Departments | | | 0 |
| lwi/hapu | 80 | 2 | 82 |
| Totals - July 2020 - 30 September 2020 | 82 | 9 | 91 |



8) Application processing time extensions used 2019-2020 versus 2020-2021

9) Consent type process

| | Last 10 year sverage 2009 2018 | July 2019 to June 2020 | September 2020 |
|--|--------------------------------------|------------------------------|-------------------|
| Total consents granted | 371 | 263 | 53 |
| Publically Notified | 9 | 1 | Ū |
| Limited-notified | 12 | 7 | 0 |
| Non-notified | 352 | 255 | 53 |
| Applications submitted on (in opposition and to be heard) | 14 | 5 | 0 |
| Application Pre-hearing resolution (%) | 8 82% | 5 100% | 0 0% |
| Hearings (no. of applications) | 1 (6) | 0 (0) | 0 (0) |
| Appeals (no. of applications) | 1 (6) | 0 (0) | 0 (0) |
| Total current consents | 4708 | 4622 | 4618 |

10) Applications returned incomplete under Section 88

For the 2020-2021 year, 3 applications have been returned incomplete under S88 of the RMA for insufficient information. Two of those applications have since been resubmitted by the applicant.

11) Deemed Permitted Activities issued

Nil



MEMORANDUM Consents & Regulatory

| Date | 13 October 2020 |
|--------------|---|
| Subject: | Consent Monitoring Annual Reports |
| Approved by: | G K Bedford, Director - Environment Quality |
| | S J Ruru, Chief Executive |
| Document: | 2593794 |

Purpose

1. The purpose of this memorandum is to advise the Council of 17 tailored compliance monitoring reports that have been prepared since the last meeting.

Executive summary

- 2. The Council considers the regular reporting of comprehensive and well-considered compliance monitoring is vital to undergird:
 - Community standing and reputation enhancement for companies that consistently attain good or high levels of environmental performance. Informed feedback is appropriate and valuable, and assists a proactive alignment of industry's interests with community and Resource Management Act 1991 expectations. Reporting describes the effective value of investment in environmental systems;
 - A respectful and responsible regard for the Taranaki region's environment and our management of its natural resources. Reporting allows evaluation and demonstration of the overall rate of compliance by sector and by consent holders as a whole, and of trends in the improvement of our environment; and
 - The Council's accountability and transparency. Reporting gives validity to investment in monitoring and to assessments of effective intervention.
 - These Council reports have been submitted to the consent holder for comment and confirmation of accuracy prior to publication. All reports provide environmental performance and administrative compliance ratings for each consent holder in relation to their activities over the period being reported and provide recommendations for the following monitoring year.
- 3. These Council reports have been submitted to the consent holder for comment and confirmation of accuracy prior to publication. All reports provide environmental performance and administrative compliance ratings for each consent holder in relation to their activities over the period being reported, and provide recommendations for the following monitoring year.

- 4. There are 17 tailored compliance monitoring reports. Within the reports 39 high, 6 good, 5 improvement required and 2 poor environmental gradings were assigned (Table 2).
- 5. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 6. In 2018 the Ministry for the Environment published Best Practice Guidelines for Compliance, Monitoring and Enforcement under the Resource Management Act 1991. These guidelines include the following recommendation: "It is good practice for councils to provide regular (e.g. annual) reports to the public on Compliance Monitoring and Enforcement (CME) activities. Council public reporting on CME gives assurance to the public that rules/policies are being enforced, and educates the public on how the council responds to non-compliance." (MfE, 2018). The Council has been providing annual compliance reports to consent holders and the public for over three decades.
- 7. Recommendations pertaining to each site or programme are set out in the relevant report. The attention of Committee members is directed to the Executive Summary at the front of this report.
- 8. In the past, memoranda presenting the compliance annual reports have also included a section outlining the stakeholder and iwi engagement within the consenting assessment process for the existing consents covered by the reports. With the completion of a full annual reporting cycle, this material on existing consents will no longer be included, as the Committee have now been fully appraised of this historical information and its inclusion would simply be repetitive. Information on iwi and stakeholder engagement in new consents will be presented separately to the Committee, within the agenda report on consenting activity.

| Year | High | Good |
|-----------|------|------|
| 2012-2013 | 59% | 35% |
| 2013-2014 | 60% | 29% |
| 2014-2015 | 75% | 22% |
| 2015-2016 | 71% | 24% |
| 2016-2017 | 74% | 21% |
| 2017-2018 | 76% | 20% |
| 2018-2019 | 83% | 13% |
| 2019-2020 | 81% | 17% |

Table 1 Historical environmental and compliance performance ratings

Table 2 List of annual reports with overall environmental performance rating

| Report Name | Overall environmental performance |
|---|---|
| 20-05 Regional Quarry Compliance Monitoring Combined Biennial Report Southern Quarries 2018-2020 | 9x High, 2x Good, 1x Imprmt req |
| 20-07 Value Timber Monitoring Programme Annual Report 2019-2020 | High |
| 20-10 STDC Eltham WWTP Monitoring Programme Annual Report 2019-2020 | High |
| 20-26 Cheal Petroleum Ltd DWI Monitoring Programme Annual Report 2019-2020 | High |
| 20-27 Westside DWI Monitoring Programme Annual Report 2019-2020 | High |
| 20-28 New Zealand Energy Corporation DWI Monitoring Programme Annual Report 2019-2020 | High |
| 20-40 Greymouth Petroleum Northern Sites Monitoring Programme Annual Report 2019-2020 | High |
| 20-42 Regional Cleanfill Monitoring Programme Annual Report 2019-2020 | 8x High, 1x Good 3x Imprmt req |
| 20-45 Todd Generation Taranaki Ltd McKee Power Plant Monitoring Programme Annual Report 2019-2020 | High |
| 20-48 RKM Farms Ltd (Piggery)Monitoring Programme Annual Report 2019-2020 | High |
| 20-51 Tawhiti Catchment Monitoring Programme Annual Report 2019-2020 | 2x High, 1x Poor |
| 20-53 NPDC Inglewood WWTP Monitoring Programme Annual Report 2019-2020 | High |
| 20-56 Cheal Petroleum Ltd – Cheal Production Station Monitoring Programme Annual Report 2019-2020 | High |
| 20-69 Ample Group Ltd Monitoring Programme Annual Report 2019-2020 | Poor |
| 20-70 Osflo Fertiliser Limited Monitoring Programme Annual Report 2019-2020 | High |
| 20-72 Regional Quarry Compliance Monitoring Combined Biennial Report Northern Quarries 2018-2020 | 8x High, 3x Good, 1x Imprmt req |
| 20-76 NPDC Coastal Structures Monitoring Programme Annual Report 2019-2020 | High |

Recommendations

That the Taranaki Regional Council:

- a) <u>receives</u> the 20-05 Regional Quarry Compliance Monitoring Combined Biennial Report Southern Quarries 2018-2020 and <u>adopts</u> the specific recommendations therein.
- b) <u>receives</u> the 20-07 Value Timber Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- c) <u>receives</u> the 20-10 STDC Eltham WWTP Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- d) <u>receives</u> the 20-26 Cheal Petroleum Ltd DWI Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- e) <u>receives</u> the 20-27 Westside DWI Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- f) <u>receives</u> the 20-28 New Zealand Energy Corporation DWI Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.

- g) <u>receives</u> the 20-40 Greymouth Petroleum Northern Sites Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- h) <u>receives</u> the 20-42 Regional Cleanfill Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- i) <u>receives</u> the 20-45 Todd Generation Taranaki Ltd McKee Power Plant Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- j) <u>receives</u> the 20-48 RKM Farms Ltd (Piggery) Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- k) <u>receives</u> the 20-51 Tawhiti Catchment Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- receives the 20-53 NPDC Inglewood WWTP Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- m) <u>receives</u> the 20-56 Cheal Petroleum Ltd Cheal Production Station Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- n) <u>receives</u> the 20-69 Ample Group Ltd Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- o) <u>receives</u> the 20-70 Osflo Fertiliser Ltd Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.
- p) <u>receives</u> the 20-72 Regional Quarry Compliance Monitoring Combined Biennial Report Northern Quarries 2018-2020 and <u>adopts</u> the specific recommendations therein.
- <u>receives</u> the 20-76 NPDC Coastal Structures Monitoring Programme Annual Report 2019-2020 and <u>adopts</u> the specific recommendations therein.

20-05 Regional Quarry Compliance Monitoring Combined Biennial Report Southern Quarries 2018-2020

- 9. This report for the period July 2018 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the environmental and consent compliance performance of various quarrying operations across Taranaki during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of these activities.
- 10. At the end of the period being reported, there were 24 active quarries being monitored by the Council across the region. These quarries held a combined total of 51 resource consents, authorising various combinations of water discharges and abstractions, discharges of cleanfill and stream modifications.
- 11. For the purposes of compliance monitoring and reporting, the Council splits quarrying operations into two distinct geographic sub-groups (Northern and Southern). Each monitoring programme is reported on biennially.
- 12. The following report details monitoring work carried out in relation to the Southern Quarries, which account for 11 of the region's 24 active quarries, as well as one quarry that was remediated during the monitoring period. This will be the fourth report to incorporate the monitoring results of this group of quarries.
- 13. The monitoring programmes for another 12 quarries will be included in a separate biennial report (Northern Quarries compliance monitoring report), which will also cover

the period July 2018 to June 2020. Civil Quarries Ltd's Everett Road quarry is reported on separately.

- 14. For each quarry, this report describes the monitoring programmes implemented by the Council to assess environmental performance during the period under review, and the results and environmental effects of the quarry's activities.
- **15.** During the monitoring period:

Bunn Earthmoving Limited, Burgess & Crowley Partnership, CD Boyd, DM & DL Bourke, Horizon Trust Limited – Waiteika Road, Ravensdown Windy Point Quarry Limited, RA Wallis Limited – Lower Glenn Road, Taunt Contracting Limited, and Vickers Quarries Limited – York Road all demonstrated an overall high level of environmental performance.

- 16. Horizon Trust Management Limited Rangitatau West Road and Horizon Trust Limited – Whenuku Road both demonstrated an overall good level of environmental performance.
- 17. Hey Trust demonstrated an overall level of environmental performance that required improvement.
- 18. For reference, in the 2017-2018 year, consent holders were found to achieve a high level of environmental performance and compliance for 76% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 20% of the consents, a good level of environmental performance and compliance was achieved.
- 19. For reference, in the 2018-2019 year, consent holders were found to achieve a high level of environmental performance and compliance for 83% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 13% of the consents, a good level of environmental performance and compliance was achieved.
- 20. In the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 21. This report includes recommendations for the 2020-2022 monitoring period for each consent holder.

20-07 Value Timber Monitoring Programme Annual Report 2019-2020

- 22. Value Timber Ltd (the Company) operates an untreated wood waste monofill located on Bristol Road at Inglewood, in the Waitara catchment. The sole source of the wood waste is from the Company's sawmilling operation in Inglewood. The Company sells most of its woodchip and sawdust as calf litter. The remaining material consisting of bark, soil and soiled woodchip/sawdust is sent to the Bristol Road site for disposal. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of the Company's activities.
- 23. The Company holds one resource consent, to discharge wood waste to land, which includes a total of 14 conditions setting out the requirements that the Company must satisfy.

24. During the monitoring period, Value Timber Ltd demonstrated an overall high level of environmental performance.

- 25. The Council's monitoring programme for the year under review included three inspections, two water samples collected for physicochemical analysis, and one wood waste sample collected for copper, chromium, arsenic, and boron (CCAB) analysis.
- 26. The monitoring showed that the site discharges were compliant with consent conditions and that the control of silt from the associated earthworks continued to be managed effectively. The grass cover in the large pre-fill gully was maintained as were the silt controls. There were no discharges of unauthorised wood waste or other materials found at inspection. There were no unauthorised incidents recording non-compliance in respect of this consent holder during the period under review.
- 27. During the year, the Company demonstrated a high level of environmental and administrative performance with the resource consent.
- 28. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 29. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 30. This report includes recommendations for the 2020-2021 year.

20-10 STDC Eltham WWTP Monitoring Programme Annual Report 2019-2020

- 31. The South Taranaki District Council (STDC) operates a municipal wastewater treatment plant (WWTP) located on Castle Street at Eltham, in the Waingongoro catchment. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the STDC's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of STDC's activities.
- 32. STDC holds one resource consent to discharge treated wastewater into an unnamed tributary of the Mangawhero Stream only in the event of high rainfall. This consent includes nine conditions setting out the requirements that they must satisfy.
- 33. During the monitoring period, South Taranaki District Council demonstrated an overall high level of environmental performance.
- 34. The Council's monitoring programme for the year under review included four inspections and associated odour surveys, four pond effluent and 33 downstream water samples collected for physicochemical analysis, and a biomonitoring survey of receiving waters.
- 35. The monitoring showed that activities at the Eltham WWTP were generally well managed. All wastewater was pumped to the Hawera WWTP and there were no consented overflows to the unnamed tributary of the Mangawhero Stream.
- 36. As in previous years, the monitoring indicated a continual improvement in water quality and the biological health of the downstream environment associated with the diversion of wastes out of the Mangawhero Stream to the Hawera WWTP in the 2010-2011 period.

- 37. During the year, STDC demonstrated a high level of environmental and administrative performance with the resource consent.
- 38. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 39. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 40. This report includes recommendations for the 2020-2021 year, including a recommendation relating to an optional review of consent 7521-1.

20-26 Cheal Petroleum Ltd DWI Monitoring Programme Annual Report 2019-2020

- 41. Cheal Petroleum Ltd (the Company) operate a number of wellsites located within their Cheal oil and gas field, south of Stratford. Each wellsite contains varying numbers of producing wells and associated production infrastructure. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) in relation to the Company's deep well injection (DWI) activities. The report details the results of the monitoring undertaken, assesses the Company's environmental performance during the period under review and the environmental effects of their DWI activities.
- 42. The Company held four resource consents for DWI activities during the review period, which included a total of 68 conditions setting out the requirements that the Company must satisfy. All four consents were exercised during the period.
- 43. During the monitoring period, the Company demonstrated a high level of environmental performance.
- 44. The Council's monitoring programme for the year under review included 11 site inspections, two injectate samples and eight groundwater samples collected for physicochemical analysis. The monitoring programme also included a significant data review component, with all injection data submitted by the Company assessed for compliance on receipt.
- 45. The monitoring showed that the Company's DWI activities were being carried out in compliance with the conditions of the applicable resource consents. There is no evidence of any issues with any injection well currently in use, or the ability of the receiving formations to accept injected fluids. The results of groundwater quality monitoring undertaken show no adverse effects of the activity on local groundwater resources. Inspections undertaken during the monitoring year found sites being operated in a professional manner and there were no Unauthorised Incidents in relation to any of the Company's DWI consents.
- 46. During the year, the Company demonstrated a high level of environmental performance and a high level of administrative performance with the resource consents.
- 47. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 48. In terms of overall environmental and compliance performance by the Company over the last several years, this report shows that the Company's performance remains at a high level.
- 49. This report includes recommendations to be implemented during the 2020–2021 monitoring period.

20-27 Westside DWI Monitoring Programme Annual Report 2019-2020

- 50. Westside New Zealand Ltd (the Company) currently operates the Manutahi, Rimu, Kauri and Pohutukawa wellsites located between Hawera and Patea, in South Taranaki. Each wellsite contains varying numbers of producing wells and associated production infrastructure. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) in relation to the Company's deep well injection (DWI) activities. The report details the results of the monitoring undertaken, assesses the Company's environmental performance during the period under review and the environmental effects of their DWI activities.
- 51. The Company held three resource consent for DWI activities during the review period, which included a total of 45 conditions setting out the requirements that the Company must satisfy.
- 52. During the monitoring period, the Company demonstrated an overall high level of environmental performance.
- 53. The Council's monitoring programme for the year under review included two inspections, two injectate samples and three groundwater samples collected for physicochemical analysis. The monitoring programme also included a significant data review component, with all injection data submitted by the Company assessed for compliance on receipt.
- 54. The monitoring showed that the Company's DWI activities were being carried out in compliance with the conditions of the applicable resource consents. There was no evidence of any issues with any injection well, or the ability of the receiving formation to accept injected fluids, during the period under review. The results of groundwater quality monitoring undertaken show no adverse effects of the activity on local groundwater resources. Inspections undertaken during the monitoring year found sites being operated in a professional manner and there were no unauthorised incidents reported in relation to the Company's DWI consents.
- 55. During the year, the Company demonstrated a high level of environmental performance and a good level of administrative performance with the resource consents.
- 56. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 57. In terms of overall environmental and compliance performance by the Company over the last three years, this report shows that the Company's performance remains at a generally high level.
- 58. This report includes recommendations to be implemented during the 2020–2021 monitoring period.

20-28 New Zealand Energy Corporation DWI Monitoring Programme Annual Report 2019-2020

- 59. NZEC Waihapa Ltd operate the Waihapa-B, Waihapa-D, Waihapa-F, and Toko-E wellsites, located south east of Stratford. NZEC Tariki Ltd and Taranaki Ventures Ltd operate the Tariki-A wellsite, located north of Stratford and Waitapu wellsite, located east of Stratford respectively. All three companies are subsidiaries of New Zealand Energy Corporation (the Company). This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) in relation to the Company's deep well injection (DWI) activities. The report details the results of the monitoring undertaken, assesses the Company's environmental performance during the period under review and the environmental effects of their DWI activities.
- 60. The Company holds six resource consents, which include a total of 85 conditions setting out the requirements that the Company must satisfy. Two of the six consents were exercised during the reporting period. A further two consents were granted and are yet to be given effect to.
- 61. During the monitoring period, the Company demonstrated a high level of environmental performance.
- 62. The Council's monitoring programme for the year under review included ten inspections, two injectate samples and nine groundwater samples collected for physicochemical analysis. The monitoring programme also included a significant data review component, with all injection data submitted by the Company assessed for compliance on receipt.
- 63. The monitoring showed that the Company's DWI activities were being carried out in compliance with the conditions of the applicable resource consents. There is no evidence of any issues with any injection well currently in use, or the ability of the receiving formation to accept injected fluids. The results of groundwater quality monitoring undertaken show no adverse effects of the activity on local groundwater resources. Inspections undertaken during the monitoring year found sites being operated in a professional manner and there were no Unauthorised Incidents in relation to any of the Company's DWI consents.
- 64. During the year, the Company demonstrated a high level of environmental performance and a high level of administrative performance with the resource consents.
- 65. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 66. In terms of overall environmental and compliance performance by the Company this report shows that the Company's performance has improved during the year under review and has returned to the high level previously seen over the last several years.
- 67. This report includes recommendations to be implemented during the 2020-2021 monitoring period.

20-40 Greymouth Petroleum Northern Sites Monitoring Programme Annual Report 2019-2020

- 68. Greymouth Petroleum Ltd (GPL) operates the Turangi Production Station located on Turangi Road at Motunui, in the Parahaki catchment. The Turangi Production Station processes oil and gas from from GPL's northern Taranaki operations, including the Ohanga, Onaero and Turangi group of wellsites. GPL also operate the Kowhai-A Production Station, located on Ngatimaru Road at Tikorangi. The Kowhai-A Production Station processes product from the Kowhai-A, B, C and D wellsites. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess GPL's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of GPL's activities.
- 69. GPL holds four resource consents in relation to the Turangi and Kowhai-A production stations, which include a total of 80 conditions setting out the requirements that GPL must satisfy. GPL holds two consents to discharge stormwater and two consents to discharge emissions related to production activities into the air. During the year under review two stormwater consents at the Turangi Production Station were surrendered after being combined, with an additional discharge, into one new consent covering the whole site.
- 70. During the monitoring period, Greymouth Petroleum Ltd demonstrated an overall high level of environmental performance.
- 71. The Council's monitoring programme for the year under review included three inspections of the Turangi and Kowhai-A production stations, along with an annual inspection of wellsites associated with the production stations. Thirteen water samples were collected for physicochemical analysis, two biomonitoring surveys of receiving waters were conducted, and two ambient air quality surveys were undertaken in relation to the Turangi Production Station.
- 72. The monitoring showed that the production station sites were well managed. Sampling of discharges and receiving waters in relation to Turangi Production Station did not find any significant adverse effects at the time of sampling, while biomonitoring in the receiving waters did not show any effect from discharges on the communities in the stream.
- 73. There were no adverse effects on the environment resulting from the exercise of the air discharge consent. Ambient air quality monitoring at the Turangi Production Station showed that levels of carbon monoxide, combustible gases, PM10 particulates, and nitrogen oxides were all below levels of concern at the time of sampling. No offensive or objectionable odours were detected beyond the boundary during inspections.
- 74. During the year, GPL demonstrated a high level of both environmental performance and administrative compliance with the resource consents.
- 75. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 76. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.

77. This report includes recommendations for the 2020-2021 year, including a recommendation relating to an optional review of consents 10169-1 and 10703-1.

20-42 Regional Cleanfill Monitoring Programme Annual Report 2019-2020

- 78. The Taranaki Regional Council (the Council) implements a co-ordinated monitoring programme for a number of cleanfill operators within the Taranaki region. Specifically this programme covers cleanfills operated by AA Contracting Ltd (AA Contracting), A & A George Family Trust (George Family), AE Riddick (Riddick), BJ & LB Bishop (Bishop), Dennis Wheeler Earthmoving Ltd, Downer EDI Works Ltd (Downer) (three sites), Gas and Plumbing Ltd (Gas and Plumbing), JW & CT Bailey Ltd (Bailey), Taranaki Trucking Company Ltd (Taranaki Trucking), and TPJ Partnership (TPJ).
- 79. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Council to assess the environmental performance at each of these sites during the period under review. The report details the results of the monitoring undertaken and assesses the environmental effects of these cleanfilling activities.
- 80. Within this programme, the 12 consented cleanfill operations monitored hold a total of 16 resource consents, which include a total of 175 conditions that the cleanfill operators must satisfy. The consents covering the activities monitored under this programme consist of one consent to discharge leachate and stormwater, four consents relating to piping, culverts and/or reclamation, and 11 consents to discharge cleanfill onto and into land.
- 81. During the period under review AA Contracting, Bailey, Bishop, Dennis Wheeler Earthmoving, Downer (Dorset Road), Downer (South Road), Gas and Plumbing, and Taranaki Trucking all demonstrated an overall high level of environmental performance.
- 82. During the period under review George Family demonstrated an overall good level of environmental performance.
- 83. An improvement was required in the environmental performance of Riddick, Downer (Veale Road) and TPJ.
- 84. The Council's monitoring programme included 33 inspections, with each site receiving either two or three scheduled inspections. The Council collected 15 water samples for physicochemical analysis during the 2019-2020 year.
- 85. No significant adverse environmental effects were observed as a result of any of the consent holders' activities at the time of the visual inspections, or during analysis of the discharge and receiving water samples. There was little, if any unauthorised material found at most of the sites, and where unauthorised materials were found, these items were, for the most part, dealt with appropriately.
- 86. During the period under review AA Contracting, Bailey, Bishop, Downer (Dorset Road), Downer (South Road), Dennis Wheeler Earthmoving, Gas and Plumbing and Taranaki Trucking all demonstrated a high level of environmental and a high administrative performance with their resource consents.
- 87. During the year, George Family demonstrated a good level of environmental performance, however an improvement was required in their administrative performance with their resource consent and regional plan rules as defined in Section 1.1.5. Prohibited material had been discharged over the tip face on one occasion, which was removed promptly. The required financial contributions were still unpaid at the end

of the year under review. At the time of writing the report, a payment schedule had been established and payments had commenced.

- 88. During the year, an improvement was required in Riddick's environmental and administrative performance with their resource consents as defined in Section 1.1.5. During the year under review contaminated materials from a subdivision development were discharged to the site and there were inadequate silt controls in place. Abatement and infringement notices were issued.
- 89. During the year, an improvement was required in Downer's level of environmental and administrative performance with their Veale Road resource consent as defined in Section 1.1.5. During the year an abatement notice was issued due to there being inadequate silt control at the site that allowed some silt and sediment to discharge over land into a nearby water body. Subsequent inspections found that the abatement notice was being complied with.
- 90. During the period under review, an improvement was required in TPJ's level of environmental and administrative performance as defined in Section 1.1.5. On one occasion unauthorised material from the Hawera High School was discharged at the site and inadequate silt controls were found, resulting in an abatement notice being issued requiring the consent holder to comply with the conditions of the consent. An infringement notice was subsequently issued. A review of Councils records also found that no prior notifications were received by Council of the disposal of materials found at the time of the two May inspections.
- 91. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 92. This report includes recommendations for the 2020-2021 monitoring period including recommendations relating to optional reviews of consents 9680-1.1 and 10748-1 (George Family), and 10202-1.1 (TPJ).

20-45 Todd Generation Taranaki Ltd McKee Power Plant Monitoring Programme Annual Report 2019-2020

- 93. Todd Generation Taranaki Ltd (Todd Generation), previously Nova Energy Ltd, operates the McKee Power Plant on Otaraoa Road near Tikorangi, bridging the Waitara and Onaero catchments. Located to the south of the McKee Production Station (which processes oil and gas from the McKee and Mangahewa groups of wellsites), the McKee Power Plant was completed and commissioned during the 2012-2014 period. This 100 MW electricity generating facility provides both peak and base load power for the national grid. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of the Company's activities.
- 94. Todd Generation holds five resource consents, which include a total of 41 conditions setting out the requirements that the Company must satisfy. The Company holds one consent to allow it to take and use water, two consents to discharge wastewater/stormwater into the Mangahewa Stream and Waitara River, one consent to discharge emissions into the air at the site, and one consent to install and use an outlet structure.

95. During the monitoring period, Todd Generation demonstrated an overall high level of environmental performance.

- 96. The Council's monitoring programme for the year under review included four inspections, six water samples collected for physicochemical analysis, and one ambient air quality analysis. Todd Generation provided water abstraction data and an air quality report as required by consent conditions.
- 97. Stormwater system inspections showed that discharges from the site complied with consent conditions at the time. Receiving water inspections and sampling showed that the discharges were not causing any adverse effects on the Mangahewa Stream at the time of monitoring. There were no adverse effects on the environment resulting from the exercise of the air discharge consents. The ambient air quality monitoring at the site showed that levels of carbon monoxide, combustible gases, and PM10 particulates were all below levels of concern at the time of sampling. There were no complaints in relation to air emissions from the site.
- 98. During the year, the Company demonstrated a high level of both environmental performance and administrative compliance with the resource consents. There were no unauthorised incidents recorded by the Council in relation to the Company's activities.
- 99. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 100. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 101. This report includes recommendations for the 2020-2021 year, including a recommendation relating to an optional review of consents 2393-3, 7920-1, 7921-1 and 7922-1.

20-48 RKM Farms Ltd (Piggery) Monitoring Programme Annual Report 2019-2020

- 102. RKM Farms Ltd (the Company) operates a piggery located on 599A South Road at Hawera in the Tangahoe, catchment. The piggery is a breeder grower and finishing operation with up to 5,000 pigs and piglets at any one time, employing between four and five full time staff.
- 103. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assess the environmental effects of the Company's activities.
- 104. The Company holds two resource consents, which include a total of 13 conditions setting out the requirements that they must satisfy. Resource consent 5108-2 allows the discharge of treated effluent into the Tawhiti Stream, and consent 5266-2 relates to the discharge of emissions into the air at this site.
- 105. During the monitoring period, RKM Farms Ltd demonstrated an overall high level of environmental performance.

- 106. The Council's monitoring programme for the year under review included three inspections and the collection of two wastewater and receiving water samples collected for physicochemical analysis.
- 107. The monitoring showed that the wastewater and receiving water samples were well within the consented limits.
- 108. During the year, the Company demonstrated a high level of environmental and administrative performance with the resource consents.
- 109. No non-compliant odour incidents were recorded during the period under review.
- 110. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 111. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level in the year under review.
- 112. This report includes recommendations for the 2020-2021 year.

20-51 Tawhiti Catchment Monitoring Programme Annual Report 2019-2020

- 113. The Tawhiti Stream catchment, east of Hawera, is the location of several industries that include a meat processing plant, a meat rendering plant, and a trout hatchery. The companies that run these industries hold a number of resource consents to allow abstraction of water, discharge of stormwater to the stream, discharge of emissions into the air, disposal of paunch material to land, and placement of a structure across the stream. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the companies' environmental and consent compliance performance during the period under review, and the results and effects of the companies' activities.
- 114. Twelve resource consents are held by the companies, which include a total of 102 conditions setting out the requirements that they must satisfy.
- 115. The Council's monitoring programme included site inspections, the collection of discharge water samples, and sampling of the receiving water body for physicochemical analysis. A hydrometric station is maintained on the stream for the continuous measurement of flow rate and temperature.

116. Silver Fern Farms Ltd (meat processing plant) demonstrated an overall poor level of environmental performance.

- 117. Silver Fern Farms Ltd holds six resource consents, to allow it to maintain a dam in and to take water from the Tawhiti Stream; to discharge to the stream and to land; and to discharge emissions into the air.
- 118. During the period under review, there was one incident reported in relation to the site, where ammonia gas was released to air. This gas was removed from the air using a water curtain and the ammonium hydroxide subsequently discharged to the stream via the site stormwater system. Investigation into this incident is ongoing and enforcement action is being considered.
- 119. Abstraction volumes complied with the consent limit, and inspections and sampling demonstrated compliance with their consents.

- 120. During the period under review, the Silver Fern Farms demonstrated a poor level of environmental and high level of administrative performance. The environmental performance rating was affected by an ammonia discharge which entered the Tawhiti Stream.
- 121. Graeme Lowe Protein Ltd (meat rendering plant) demonstrated an overall high level of environmental performance.
- 122. Graeme Lowe Protein Ltd holds four resource consents, to allow it to take from and discharge to the Tawhiti Stream, and to discharge emissions into the air.
- 123. In general, compliance monitoring indicated that the consent holder was meeting the requirements of their consents.
- 124. Abstraction volumes complied with the consent limit, and inspections demonstrated compliance with their consents.
- 125. During the period under review, overall, Graeme Lowe Protein demonstrated a high level of environmental and high level of administrative performance with the resource consents as defined in section 1.1.4.
- 126. Taranaki Fish and Game Council (trout hatchery) demonstrated an overall high level of environmental performance.
- 127. The organisation holds two resource consents, to allow it to take and use water from, and to discharge to, the Tawhiti Stream. Two inspections were conducted during the review period, which indicated that contaminants in the discharge to the Tawhiti Stream were minimal and had no significant environmental effect.
- 128. During the period under review, there were no unauthorised incidents reported in relation to activities at the site.
- 129. During the period under review, the Taranaki Fish and Game Council demonstrated a high level of environmental and high level of administrative performance with the resource consents as defined in section 1.1.4.
- 130. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 131. Physico-chemical surveys of Tawhiti Stream, carried out on four occasions in dry and wet weather conditions during the review period, showed no adverse effect on the stream as the result of activities at the sites of Silver Fern Farms Ltd, Graeme Lowe Protein Ltd and Taranaki Fish and Game.
- 132. This report contains recommendations for the 2020-2021 year.

20-53 NPDC Inglewood WWTP Monitoring Programme Annual Report 2019-2020

133. The New Plymouth District Council (NPDC) operates a municipal wastewater treatment plant (WWTP) located on Lincoln Road at Inglewood, in the Kurapete catchment. This report for the period July 2018 to June 2019 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of NPDC's activities.

- 134. NPDC holds one resource consent to intermittently discharge treated wastewater to the Kurapete Stream, which includes a total of nine conditions setting out the requirements that they must satisfy.
- 135. During the monitoring period, NPDC demonstrated an overall high level of environmental performance.
- 136. The Council's monitoring programme for the year under review included three scheduled and one follow-up inspection, wastewater effluent analyses, and one biological survey of the receiving waters of the Kurapete Stream.
- 137. NPDC's maintenance programme continues to generally enhance the operation and appearance of the plant and effectively control any produced odour. No complaints were received in relation to the operation of the WWTP. Regular inspections indicated no immediate problems with the performance of the plant.
- 138. One consented overflow was recorded during the monitoring year. No adverse environmental impacts were observed in the receiving waters as a result of this.
- 139. During the year, NPDC demonstrated a high level of environmental and administrative performance with the resource consents.
- 140. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 141. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 142. This report includes recommendations for the 2020-2021 year.

20-56 Cheal Petroleum Ltd – Cheal Production Station Monitoring Programme Annual Report 2019-2020

- 143. Cheal Petroleum Ltd (the Company), a subsidiary of Tamarind NZ Onshore Ltd, operates a petrochemical production station located on Mountain Road at Ngaere, in the Waingongoro catchment. The Cheal Production Station processes oil and gas from the Cheal group of wellsites. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of the Company's activities.
- 144. The Company holds three resource consents in relation to the Cheal Production Station, which includes a total of 42 conditions setting out the requirements that the Company must satisfy. The Company holds one consent to take and use groundwater for water flooding purposes, one consent to discharge stormwater and treated waste water onto land in circumstances where it may subsequently enter an unnamed tributary of the Mangawharawhara Stream, and one consent to discharge emissions related to production activities into the air at the site.
- 145. During the monitoring period, Cheal Petroleum Ltd demonstrated an overall high level of environmental performance.

- 146. The Council's monitoring programme for the year under review included five inspections, six water samples collected for physicochemical analysis, and two ambient air quality analyses.
- 147. Stormwater system inspections showed that discharges from the sites complied with consent conditions. Receiving water sampling showed that the discharges complied with consent conditions. No adverse effects were observed in the tributary of the Mangawharawhara Stream at the time of monitoring.
- 148. There were no adverse effects on the environment found as a result of the exercise of the air discharge consent. Ambient air quality monitoring at the site showed that levels of carbon monoxide, combustible gases, PM10 particulates, and nitrogen oxides were all below levels of concern at the time of sampling. No offensive or objectionable odours were detected beyond the boundary during inspections.
- 149. During the year, the Company demonstrated a high level of both environmental performance and administrative compliance with the resource consents.
- 150. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 151. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 152. This report includes recommendations for the 2020-2021 year.

20-69 Ample Group Ltd Monitoring Programme Annual Report 2019-2020

- 153. Ample Group Ltd (the Company) operate an abattoir and rendering plant, located on Mountain Road at Stratford, in the Kahouri Stream catchment, a tributary of the Patea River. The Company currently processes only beef. Wastewater is treated in a two pond system, which is either irrigated to land when conditions allow, or to the Kahouri Stream, ideally during high flow conditions. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of the Company's activities.
- 154. The Company holds six resource consents, which include a total of 92 conditions setting out the requirements that the Company must satisfy. The Company holds one consent to allow it to take and use water, two consents to discharge effluent and stormwater into the Kahouri Stream, two consents to discharge wastewater and degenerating product to land, and one consent to discharge emissions into the air at this site.

155. During the monitoring period, Ample Group Ltd demonstrated an overall poor level of environmental performance.

156. The Council's monitoring programme for the year under review included four inspections, 12 water samples collected for physicochemical analysis, four wastewater samples collected for physicochemical analysis, four hydrological gaugings and two, three site biomonitoring surveys.

- 157. The monitoring indicated that while environmental performance was good in some areas, there were also areas that needed improvement. There needs to be a focus on minimising the generation of wastewater as a significant amount of wastewater appears to be sourced from groundwater infiltration of the wastewater ponds. Water abstraction levels were not recorded due to a faulty datalogger. The discharge of wastewater into the Kahouri Stream did not meet the required dilution level but did not cause any noticeable impact on the macroinvertebrate communities of the Kahouri Stream. The irrigation of wastewater onto land could be further improved, with better rotation of paddocks to prevent excessive amounts of wastewater being discharged onto the same paddock. There was no evidence of excessive leaching of irrigation water into nearby waterbodies, with only minor changes in water quality parameters for the unnamed tributary and Kahouri Stream as they flowed through the Company's site.
- 158. The rendering plant did not operate during the period under review and this has significantly reduced odour issues with no odour complaints related to the site. Furthermore, disposal of dead stock/material is being achieved by sending all material offsite as opposed to burying waste, further reducing the potential for odour to be generated at the site, and the flow of contaminates to groundwater.
- 159. There were three incidents of non-compliance during the period under review. Firstly, there was an incident in relation to a faulty datalogger. The purpose of the datalogger was to record water abstraction from the Kahouri Stream. Its failure prevented assessment of several consent conditions. The issue was investigated, and an abatement and infringement notice issued against the Company. Secondly, the wastewater records indicated that there were several instances of discharges to land that exceeded the maximum allowable 15 day rolling average. An infringement notice was issued for the non-compliance. Thirdly, the wastewater records indicated that discharges to the Kahouri Stream did not meet the 1:100 dilution factor. At time of preparation of this report, the Company is under an abatement notice for non-compliance for this condition and an infringement notice for the exceedance is being considered by the Council.
- 160. During the year, the Company demonstrated a level of environmental and administrative performance that was poor overall. While there were no significant adverse environmental effects arising from the Company's non-compliance, the ongoing issues of major and minor non-compliance required repeated enforcement interventions by the Council.
- 161. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 162. This report includes recommendations for the 2020-2021 year.

20-70 Osflo Fertiliser Limited Monitoring Programme Annual Report 2019-2020

- 163. Osflo Fertiliser Limited (the Company) operates a poultry litter storage, blending and distribution facility. This is located at 1319 Mountain Road, Inglewood, in the Waiongana catchment. The poultry litter is collected from farms around the Taranaki region and is sold as a registered fertiliser.
- 164. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the Company's environmental and consent compliance performance during the period under review.

The report also details the results of the monitoring undertaken and assesses the environmental effects of the Company's activities.

165. The Company holds three resource consents, which include a total of 17 conditions setting out the requirements that the Company must satisfy. The Company holds one consent to discharge effluent to land via soakage. One consent to discharge stormwater to land via soakage where it may enter an unnamed tributary of the Waiongana Stream, and one consent to discharge emissions into the air at this site.

166. During the monitoring period, the Company demonstrated an overall high level of environmental performance.

- 167. The Council's monitoring programme for the year under review included four inspections, including odour surveys and five water samples collected for physicochemical analysis.
- 168. The water samples indicated that the Company were in compliance with consent defined conditions on the four occasions they were collected. No objectionable odours were found beyond the boundary of the site during the inspections. One odour complaint was received about the Company during this monitoring period, which was unsubstantiated.
- 169. There were no unauthorised incidents recording non-compliance in respect of this consent holder during the period under review.
- 170. During the year, the Company demonstrated a high level of environmental and administrative performance with the resource consents.
- 171. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 172. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level in the year under review.
- 173. This report includes recommendations for the 2020-2021 year.

20-72 Regional Quarry Compliance Monitoring Combined Biennial Report Northern Quarries 2018-2020

- 174. This report for the period July 2018 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess the environmental and consent compliance performance of various quarrying operations across Taranaki during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of these activities.
- 175. At the end of the period being reported, there were 24 active quarries being monitored by the Council across the region. These quarries held a combined total of 51 resource consents, authorising various combinations of water discharges and abstractions, discharges of cleanfill and stream modifications.
- 176. For the purposes of compliance monitoring and reporting, the Council splits quarrying operations into two distinct geographic sub-groups (Northern and Southern). Each monitoring programme is reported on biennially.

- 177. The following report details monitoring work carried out in relation to Northern Quarries, which account for 12 of the region's 24 active quarries. This will be the fourth report to incorporate the monitoring results of this group of quarries.
- 178. The monitoring programmes for another 11 quarries (plus one since remediated) will be included in a separate biennial report (Southern Quarries Compliance Monitoring Report), which also covers the period July 2018 to June 2020. Civil Quarries Ltd's Everett Road quarry is reported on separately.
- 179. For each quarry, this report describes the monitoring programmes implemented by the Council to assess environmental performance during the period under review, and the results and environmental effects of the quarry's activities.
- 180. During the monitoring period: AA Contracting Ltd, Jones Quarry Ltd – Kekeua Road, GR & LJ Jones – Waitara Quarry, Gibson Family Trust, Goodin AG Ltd, Taranaki Trucking Company Ltd, Whitaker Civil Engineering Ltd and Wiremu Road Quarry Ltd all demonstrated an overall high level of environmental performance.
- 181. Ferndene Quarries Ltd, Jones Quarry Ltd Hydro Road and R J Dreaver quarry all demonstrated an overall good level of environmental performance.
- 182. Jones Quarry Ltd Uruti demonstrated an overall level of environmental performance that required improvement.
- 183. Ferndene Quarries was issued an abatement notice as there were large amounts of unauthorised materials present in the cleanfill, repeatedly over the monitoring period. Following the abatement notice, an inspection showed the cleanfill was compliant. Jones Quarry Ltd - Hydro Road were also found to be repeatedly non-compliant due to unauthorised material in the cleanfill. An abatement notice was issued and the Company made improvements to the site to reduce the possibility of cleanfill contamination. R J Dreaver quarry had several instances of discharge of sediment-laden stormwater and some unauthorised materials were present in the cleanfill. They have since installed a flow control valve before discharge to the stream, and immediately dealt with the non-compliant cleanfill material. Jones Quarry Ltd - Uruti was issued an abatement notice due to a discharge of sediment-laden wash water, discharge of sediment-laden stormwater due to lack of silt and sediment controls, and unauthorised stockpiling of aggregate. There have also been delays in installing a flowmeter as part of their water take consent. Follow up inspections showed the Company is making improvements in the management and maintenance of the site and have ceased taking water.
- 184. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 185. This report includes recommendations for the 2020-2022 monitoring period for each consent holder.

20-76 NPDC Coastal Structures Monitoring Programme Annual Report 2019-2020

186. New Plymouth District Council (NPDC) is responsible for various coastal permits around the New Plymouth area. This report for the period July 2019 to June 2020 describes the monitoring programme implemented by the Taranaki Regional Council (the Council) to assess NPDC's environmental and consent compliance performance during the period under review. The report also details the results of the monitoring undertaken and assesses the environmental effects of NPDC's coastal structures.

187. NPDC holds 46 resource consents which are assessed in this monitoring programme. Each consent includes conditions setting out the requirements that NPDC must satisfy. There are 26 permits relating to coastal protection, six permits relating to stormwater outfalls, five permits for access structures, three permits covering stream outlet structures, three permits for bridges and three permits for outfall structures. NPDC holds additional coastal permits which are assessed and reported on within separate site specific monitoring programmes.

188. During the monitoring period, NPDC demonstrated an overall high level of environmental performance.

- 189. The Council's monitoring programme for the period under review included an annual inspection of each of the structures.
- 190. Based on the visual inspections that were carried out, no major issues were found with the structures themselves, although some of the structures required minor repairs. Some instances of scour or erosion were identified, though these were generally minor. An exception to this was the considerable erosion occurring along the Waitara East beach shoreline. However, it is not yet clear whether this erosion has been influenced by the Waitara river mouth groyne/mole structures, or whether it is occurring independently. Further investigation is required to establish the cause(s) of this erosion and identify remedial measures.
- 191. In order to better detect changes such as these, which can occur gradually over long periods of time, additional, survey based monitoring will be undertaken as part of the monitoring programme from 2020-2021. This additional monitoring will be associated with the significant structures that have greater potential for influencing coastal processes such as seawalls and groynes. Conversely, the inspection frequency for minor structures will be reduced to biennial, from 2020-2021. These changes are outlined within the report.
- 192. During the year, NPDC demonstrated a high level of environmental and administrative performance with their coastal structure resource consents. During the year under review there were no significant incidents or non-compliances with consent conditions.
- 193. For reference, in the 2019-2020 year, consent holders were found to achieve a high level of environmental performance and compliance for 81% of the consents monitored through the Taranaki tailored monitoring programmes, while for another 17% of the consents, a good level of environmental performance and compliance was achieved.
- 194. In terms of overall environmental and compliance performance by the consent holder over the last several years, this report shows that the consent holder's performance remains at a high level.
- 195. This report includes recommendations for the 2020-2021 year, including recommendations to exercise the optional review clauses of five consents.

Decision-making considerations

196. Part 6 (Planning, decision-making and accountability) of the *Local Government Act* 2002 has been considered and documented in the preparation of this agenda item. The

recommendations made in this item comply with the decision-making obligations of the *Act*.

Financial considerations—LTP/Annual Plan

197. This memorandum and the associated recommendations are consistent with the Council's adopted Long-Term Plan and estimates. Any financial information included in this memorandum has been prepared in accordance with generally accepted accounting practice.

Policy considerations

198. This memorandum and the associated recommendations are consistent with the policy documents and positions adopted by this Council under various legislative frameworks including, but not restricted to, the *Local Government Act* 2002, the *Resource Management Act* 1991 and the *Local Government Official Information and Meetings Act* 1987.

lwi considerations

199. This memorandum and the associated recommendations are consistent with the Council's policy for the development of Māori capacity to contribute to decision-making processes (schedule 10 of the *Local Government Act 2002*) as outlined in the adopted long-term plan and/or annual plan. Similarly, iwi involvement in adopted work programmes has been recognised in the preparation of this memorandum.

Legal considerations

200. This memorandum and the associated recommendations comply with the appropriate statutory requirements imposed upon the Council.

| Report Name | PDF Number | Reporting period |
|---|---------------|------------------|
| 20-05 Regional Quarry Compliance Monitoring Combined Biennial Report Southern Quarries 2018-2020 | 2588874 | 2018-2020 |
| 20-07 Value Timber Monitoring Programme Annual Report 2019-2020 | 2555636 | 2019-2020 |
| 20-10 STDC Eltham WWTP Monitoring Programme Annual Report 2019-2020 | 2572225 | 2019-2020 |
| 20-26 Cheal Petroleum Ltd DWI Monitoring Programme Annual Report 2019-2020 | 2580020 | 2019-2020 |
| 20-27 Westside DWI Monitoring Programme Annual Report 2019-2020 | 2592140 | 2019-2020 |
| 20-28 New Zealand Energy Corporation DWI Monitoring Programme Annual Report 2019-2020 | 2579651 | 2019-2020 |
| 20-40 Greymouth Petroleum Northern Sites Monitoring Programme Annual Report 2019-2020 | 2593015 | 2019-2020 |
| 20-42 Regional Cleanfill Monitoring Programme Annual Report 2019-2020 | 2569927 | 2019-2020 |
| 20-45 Todd Generation Taranaki Ltd McKee Power Plant Monitoring Programme Annual Report 2019- 2020 | 2567574 | 2019-2020 |
| 20-48 RKM Farms Ltd (Piggery) Monitoring Programme Annual Report 2019-2020 | 2562050 | 2019-2020 |
| 20-51 Tawhiti Catchment Monitoring Programme Annual Report 2019-2020 | 2554210 | 2019-2020 |

Appendices/Attachments

| Report Name | PDF Number | Reporting period |
|--|---------------|------------------|
| 20-53 NPDC Inglewood WWTP Monitoring Programme Annual Report 2019-2020 | 2561936 | 2019-2020 |
| 20-56 Cheal Petroleum Ltd- Cheal Production Station Monitoring Programme Annual Report 2019-2020 | 2587367 | 2019-2020 |
| 20-69 Ample Group Ltd Monitoring Programme Annual Report 2019-2020 | 2587207 | 2019-2020 |
| 20-70 Osflo Fertiliser Limited Monitoring Programme Annual Report 2019-2020 | 2576983 | 2019-2020 |
| 20-72 Regional Quarry Compliance Monitoring Combined Biennial Report Northern Quarries 2018-2020 | 2583252 | 2018-2020 |
| 20-76 NPDC Coastal Structures Monitoring Programme Annual Report 2019-2020 | 2590178 | 2019-2020 |



Purpose

- 1. The purpose of this memorandum is to allow the Council to consider and receive the summary of the incidents, compliance monitoring non-compliances and enforcement for the period 14 August 2020 to 23 September 2020.
- 2. The annual inspection for farm dairy effluent monitoring programme commences in September each year and usually finishes around March, however follow up inspections and winter milking inspections are also carried out during the rest of the year.

Executive summary

Incidents

- 3. There are fifty nine (59) incidents reported.
- 4. Twenty four (24) of the incidents were found to be compliant and twenty four (24) were found to be non-compliant. Eleven (11) of the incidents reported relate to non-compliances from previous periods (updates). The action taken on the incidents is set out for Members information.

Compliance monitoring non-compliances

- 5. There are forty six (46) compliance monitoring non-compliances reported. Thirty six (36) of the compliance monitoring non-compliances reported are updates from previous periods.
- 6. Twenty nine (29) of the non-compliances reported are as a result of the annual dairy inspection round.

Recommendations

That the Taranaki Regional Council:

- a) <u>receives</u> this memorandum Incident, Compliance Monitoring Non-compliances and Enforcement Summary - 14 August 2020 to 23 September 2020
- b) <u>receives</u> the summary of the incidents, compliance monitoring non-compliances and enforcement for the period from 14 August 2020 to 23 September 2020, <u>notes</u> the action taken by staff acting under delegated authority and <u>adopts</u> the recommendations therein.

Background

- 7. The Council receives and responds to pollution events and public complaints throughout the year. Consent compliance monitoring undertaken can also identify noncompliance. This information is recorded in the IRIS database together with the results of investigations and any follow-up actions. Such incidents and non-compliances are publicly reported to the Council through the Consents and Regulatory Committee via the Incidents, Compliance Monitoring Non-compliances and Enforcement Report or the Annual Compliance Monitoring Reports.
- 8. Attached is the summary of the Incidents, Compliance Monitoring Non-compliances and Enforcement for the period from 14 August 2020 to 23 September 2020.
- 9. Staff have been delegated by the Council to undertake enforcement actions. The enforcement policy and procedures are approved by the Council and then consistently implemented and reported on by staff.

Disclosure Restrictions

10. The incident register information presentation was reviewed in 2014-2015 to increase reader understanding in this complex area. The first section addresses compliant incidents and can be publically discussed. The second section provides an update on non-compliant incidents from previous meetings and where an incident has been resolved it can be publically discussed. The third and fourth sections provide information on non-compliant incidents and non-compliances found during compliance monitoring during the period that are still under investigation and staff are limited in terms of public disclosure of information, while the investigation is ongoing and enforcement responses have not been determined. The incident flow chart and definition of terms provide further operational detail.

Discussion

11. Council responds to all complaints received with most complaints responded to within four hours. This usually involves a site visit. Responses to complaints and non-compliances with rules in the Council's regional plans, resource consents and the Resource Management Act 1991 are recorded in the IRIS database. Where necessary, appropriate advisory or enforcement actions are undertaken. The latter may include issuing an inspection, abatement or infringement notice, or initiating a prosecution. Where an infringement notice or prosecution is possible, details of the information in the Incidents, Compliance Monitoring Non-compliances and Enforcement agenda item and staff comment will be restricted for legal disclosure reasons. Further information will be

provided at a later date to the Council and for prosecutions a detailed report will be provided for information purposes, in the confidential section of the agenda.

- 12. A summary of Incidents, Compliance Monitoring Non-compliances and Enforcement for the period 14 August 2020 to 23 September 2020 is attached. The 'compliant' incidents are presented first in a table and the 'non-compliant' incidents are presented after in a more detailed summary, followed by the compliance monitoring non-compliances.
- 13. Generally incidents in the 'compliant' table have a recommendation of 'no further action'. However, an incident is considered 'compliant' until such time as a non-compliance is found. Therefore occasionally an incident in the 'compliant' table will have a recommendation of 'investigation continuing', if an ongoing investigation is still underway to confirm compliance.
- 14. A series of graphs are also attached comparing the number of incidents between 2016-2017 and 2020-2021, and also showing how the incidents are tracking in 2020-2021 in relation to environment type and compliance status. There is a graph showing the non-compliances found during compliance monitoring. There is also a graph showing enforcement action taken to date during 2020-2021.
- 15. The data in the graphs for 2020-2021 to date is showing that there are more incidents but less compliance monitoring non-compliances.

Decision-making considerations

16. Part 6 (Planning, decision-making and accountability) of the *Local Government Act* 2002 has been considered and documented in the preparation of this agenda item. The recommendations made in this item comply with the decision-making obligations of the *Act*.

Financial considerations—LTP/Annual Plan

17. This memorandum and the associated recommendations are consistent with the Council's adopted Long-Term Plan and estimates. Any financial information included in this memorandum has been prepared in accordance with generally accepted accounting practice.

Policy considerations

18. This memorandum and the associated recommendations are consistent with the policy documents and positions adopted by this Council under various legislative frameworks including, but not restricted to, the *Local Government Act* 2002, the *Resource Management Act* 1991 and the *Local Government Official Information and Meetings Act* 1987.

lwi considerations

19. This memorandum and the associated recommendations are consistent with the Council's policy for the development of Māori capacity to contribute to decision-making processes (schedule 10 of the *Local Government Act 2002*) as outlined in the adopted longterm plan and/or annual plan. Similarly, iwi involvement in adopted work programmes has been recognised in the preparation of this memorandum.

Legal considerations

20. This memorandum and the associated recommendations comply with the appropriate statutory requirements imposed upon the Council.

Appendices/Attachments

Document 1081324: Incident flowchart and terms explained

Document 2602880: Incident and Enforcement Graphs to 31 August 2020

Document 2603178: Incidents and Enforcement Summary 14 August 2020 to 23 September 2020



Terms explained

Compliance rating

| Compliant | After investigation the incident was found to be <u>compliant</u> with environmental standards or other regulations, permitted rules in a regional plan (e.g. RFWP, RAQP, RCP allowed), a resource consent and/or the Resource Management Act 1991. |
|---------------|--|
| Non-compliant | After investigation the incident was found to be <u>non-compliant</u> with environmental standards or other regulations, rules in a regional plan, a resource consent and/or the Resource Management Act 1991 |

Origin/Notification:

| Complaint | Notification of incident received from public. |
|-----------------------------|---|
| Self notification | Notification of incident received from the responsible party. |
| Third Party Notification | Notification of incident received from third party such as New Zealand Fire, District Council etc. |
| TRC Staff monitoring | Notification of incident found during routine compliance monitoring. |
| TRC Staff notification | Notification of incident found during unrelated monitoring/field work. |
| Action/s Taken: | |
| 14 day Letter | A letter was sent requesting an explanation for the non-compliance and why enforcement action should not be considered. The recipient is given 14 days to reply. |
| Abatement Notice | A notice was issued requiring something to be undertaken or something to cease to ensure compliance with Rules in the regional plans, resource consent or Resource Management Act 1991. Notice must be complied with or further enforcement action can be considered. |
| Consent application | A consent application has been received as a result of the investigation. |
| Consent change required | During the investigation it was found that a consent change was required. |
| Emergency Works | Emergency works was allowed under section 330 of the RMA. Often a subsequent resource consent is required. |
| Enforcement Order | An enforcement order has been issued by the Environment Court requiring action to be undertaken or something to cease. Notice must be complied with or further enforcement action can be |

| | considered. |
|---|---|
| Infringement Notice (\$xxx.xx) | An infringement notice was issued under Section 338(1)(a) of the Resource Management Act 1991 and Councils delegated authority. |
| Inspection Notice | An inspection was undertaken and a notice of advice/instruction was issued to landowner/alleged offender. |
| Inspection/no notice issued | An inspection was undertaken, however no inspection notice was issued as there was no alleged offender/landowner to issue one to (natural event, unsourced etc). |
| Interim Enforcement Order | An interim enforcement order has been issued by the Environment Court requiring action to be undertaken or something to cease. Notice must be complied with or further enforcement action can be considered. |
| Meeting with Company | A meeting was held with the Company to discuss the incident and ways to resolve any issues. |
| None | No action was required. |
| Not Substantiated | The incident could not be substantiated (i.e. it is not likely/possible/probable that the alleged incident could have taken place). |
| Phone call | A phone call was made to the alleged offender/authority. |
| Prosecution | A prosecution is being initiated for this incident. |
| Referral to Appropriate Authority | The incident was referred to the appropriate authority (District Council, Department of Conservation etc). |

Recommendations to Council

| Investigation continuing | Outcome has not been finalised. Investigation is continuing on this incident, information/evidence still being gathered. Further action, including enforcement are being considered and therefore legally all information cannot be reported on this incident at this stage. These incidents will continue to be reported as updates in the following agendas. |
|-----------------------------|--|
| No Further Action | Investigation is completed, any required enforcement action has been undertaken and no further action is required. |
| No Further Action | Investigation is completed, any required enforcement action has been |
| At This Stage | undertaken and further action may be required at a later date. |
| No Further | Investigation is completed, any required enforcement action has been |
| Action/Costs | undertaken and no further action is required. Costs will be recovered |
| Recovered | from the alleged offender for the investigation. |

| No further Action at | Investigation is completed, any required enforcement action has been |
|----------------------|--|
| this Stage/Costs | undertaken and further action may be required at a later date |
| Recovered | (reinspection of Abatement Notice etc). Costs will be recovered from |
| | the alleged offender for the investigation. |

Defences under Sections 340 and 341 of the Resource Management Act 1991

Sometimes no enforcement action is undertaken against an alleged offender for a noncompliant incident as they have a defence under Section 340 of the Resource Management Act 1991 including reasons such as:

- the defendant can prove that he or she did not know, and could not reasonably be expected to have known that the offence was to be or was being committed, or
- that he or she took all reasonable steps to prevent the commission of the offence, or
- the action or event could not reasonably have been foreseen or been provided against by the defendant.



Incident and Enforcement Graphs to 31 August 2020





61







| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Compliance Status | Recommendation |
|------------------|-------------------------|--|-----------|-------------------------------|-------------------|---------------------------------|-------------------|
| 14 Aug 2020 | 3301-21-060 IN/40212 | Alleged Earthworks - Namu Road, Opunake | Complaint | Michael Charles Drought | | RFWP Allowed | No Further Action |
| 15 Aug 2020 | 3301-21-064 IN/40223 | Alleged Dust (Pollen) - Mangorei Road, New Plymouth | Complaint | Natural Event | | Not Applicable/Natural Event | No Further Action |
| 16 Aug 2020 | 3301-21-066 IN/40227 | Alleged Odour - Mokau Road, Uruti | Complaint | Remediation (NZ) Limited | R2/5839-2 | Consent Compliance | No Further Action |
| 17 Aug 2020 | 3301-21-068 IN/40316 | Alleged Odour - Smart Road, New Plymouth | Complaint | New Plymouth District Council | R2/4622-1 | Consent Compliance | No Further Action |
| 17 Aug 2020 | 3301-21-069 IN/40431 | Alleged Odour - Mokau Road, Uruti | Complaint | Remediation (NZ) Limited | R2/5839-2 | Consent Compliance | No Further Action |
| 17 Aug 2020 | 3301-20-070 IN/40432 | Alleged Odour - Pukaka Street, New Plymouth | Complaint | Unsourced | | RAQP Allowed | No Further Action |
| 18 Aug 2020 | 3301-21-062 IN/40229 | Alleged Odour - Mokau Road, Uruti | Complaint | Remediation (NZ) Limited | R2/5839-2 | Consent Compliance | No Further Action |
| 18 Aug 2020 | 3301-21-074 IN/40230 | Alleged Odour - Oropuriri Road, Bell Block | Complaint | JQ Landscaping Supplies | | RAQP Allowed | No Further Action |
| 25 Aug 2020 | 3301-21-078 IN/40320 | Alleged Discoloured stream - Pukenui Street, New Plymouth | Complaint | Unsourced | | RFWP Allowed | No Further Action |
| 26 Aug 2020 | 3301-21-075 IN/40272 | Alleged Pig in stream - East Road, Toko | Complaint | Laurence Cooke | | RFWP Allowed | No Further Action |

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Compliance Status | Recommendation |
|------------------|-------------------------|--|---------------------------------------|--------------------------------|-------------------|--------------------|-------------------|
| 27 Aug 2020 | 3301-21-079 IN/40279 | Alleged Earthworks - Allison Street, Opunake | Complaint | Brian & Sara Sinclair | | RFWP Allowed | No Further Action |
| 27 Aug 2020 | 3301-21-086 IN/40282 | Alleged Backyard rubbish - Nelson Street, Waitara. | Complaint | lan Cooper | | RFWP Allowed | No Further Action |
| 27 Aug 2020 | 3301-21-087 IN/40283 | Alleged Sewage discharge - Weld Road, Oakura | Complaint | Ben & Casey Plumber | | RFWP Allowed | No Further Action |
| 28 Aug 2020 | 3301-21-112 IN/40455 | Alleged Burnt out vehicle - Ngutuwera Road, Waitotara | Complaint | Unsourced | | RFWP Allowed | No Further Action |
| 02 Sep 2020 | 3301-21-077 IN/40312 | Alleged Earthworks - Ngatimaru Road, Tikorangi | Complaint | Lewese Hicks | | RFWP Allowed | No Further Action |
| 02 Sep 2020 | 3301-21-080 IN/40321 | Alleged Osflo odour - Mountain Road, Inglewood | Complaint | Osflo Spreading Industries Ltd | R2/10578- 1.0 | Consent Compliance | No Further Action |
| 02 Sep 2020 | 3301-21-084 IN/40435 | Alleged Odour - Mokau Road, Uruti | Complaint | Remediation (NZ) Limited | R2/5839-2 | Consent Compliance | No Further Action |
| 03 Sep 2020 | 3301-21-089 IN/40437 | Alleged Odour - SH3, Inglewood | Complaint | Osflo Spreading Industries Ltd | | RAQP Allowed | No Further Action |
| 07 Sep 2020 | 3301-21-093 IN/40433 | Alleged Black smoke - Mountain Road, Eltham | TRC Staff Compliance Monitoring | JJ & KJ Cossey | | RAQP Allowed | No Further Action |

| Compliant Incidents for the period 14 Aug 2020 to 23 Sep |
|--|
|--|

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Compliance Status | Recommendation |
|------------------|-------------------------|--|-----------|---------------------------------|-------------------|---------------------------------|-------------------|
| 10 Sep 2020 | 3301-21-097 IN/40378 | Alleged Dust - South Road, Hawera | Complaint | Andy Sybrandy Warren Riddick | | RFWP Allowed | No Further Action |
| 17 Sep 2020 | 3301-21-102 IN/40415 | Alleged Dead fish - Lake Rotomanu - New Plymouth | Complaint | Natural Event | | Not Applicable/Natural Event | No Further Action |
| 18 Sep 2020 | 3301-21-100 IN/40412 | Alleged Dairy effluent - SH45, Mania | Complaint | Mark Stevenson | R2/4374-1 | Consent Compliance | No Further Action |
| 19 Sep 2020 | 3301-21-103 IN/40403 | Alleged Smoke - Glover Road, Hawera | Complaint | Simeon Prestidge | | RAQP Allowed | No Further Action |
| 23 Sep 2020 | 3301-21-115 IN/40457 | Alleged Cows access to Waiwhakaiho River - New Plymouth | Complaint | Unsourced | | RFWP Allowed | No Further Action |

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|---------------------------|--------------|------------------------------|-------------------|-----------------------|----------------|
| 16 Oct 2019 | 3301-20-303 | Sewage discharge - Urenui | TRC Staff | John Honeyfield (71950) | | EAC-23440 - Abatement | Investigation |
| <u>Update</u> | IN/38998 | Estuary - Urenui | Notification | Unsourced (9768) | | Notice | Continuing |

Comments: During a Citizen Science project undertaken with Te Rūnanga o Ngāti Mutunga, samples of stormwater that discharges into the Urenui Estuary were taken. Subsequent analysis of the samples found that there was strong evidence of human sewage contamination. A meeting was held with New Plymouth District Council (NPDC), Te Rūnanga o Ngāti Mutunga and Taranaki District Health Board where the results were discussed. NPDC have undertaken to investigate the stormwater system and any possible problem areas to try to locate the source of the contamination. An update report was received outlining that further water sampling has identified 33 possible sources, which were further investigated. As a result of the investigation NPDC prepared an action plan which outlines remedial works to be undertaken to resolve the problem. NPDC and TRC have undertaken a series of inspections and sampling to more specifically locate the pathways of contamination. One abatement notice has been issued requiring works to be undertaken to ensure compliance with the Regional Fresh Water Plan for Taranaki. Reinspection will be undertaken to ascertain compliance.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|--|-----------|---|-------------------|--|-----------------------------|
| 09 Jun 2020 <u>Update</u> | 3301-20-503 IN/39884 | Unauthorised dumping and burning - Lower King Road, Bell Block | Complaint | Clelands Construction Ltd (22615) Jeremy & Racheal Cottam (24684) Maxwell Gray (55411) Offshore Plumbing & Pipeline (55449) Papa Rererangi i Puketapu Limited (NP Airport) (55471) | | EAC-23450 - Abatement Notice EAC-23445 - Abatement Notice EAC-23422 - Abatement Notice EAC-23390 - Abatement Notice EAC-23384 - Explanation Requested - Letter EAC-23382 - Explanation Requested - Letter EAC-23376 - Explanation Requested - Letter EAC-23374 - Explanation Requested - Letter EAC-23373 - Explanation Requested - Letter EAC-23373 - Explanation Requested - Letter EAC-23370 - Abatement Notice EAC-23359 - Abatement Notice | Investigation Continuing |

Comments: A complaint was received concerning a smokey fire at a property on Lower King Road, Bell Block. Investigation found that a fire was burning on the property, with generators and lights set up around the fire area. Larges amounts of rubbish were observed being transported onto the property. Trucks were followed and it was found that materials from the demolition of the old New Plymouth Airport terminal were being dumped and burnt on the property. An inspection of the property was undertaken and it was found that unauthorised materials were being dumped and burnt. Photographs and samples were taken. Abatement notices were issued requiring the deposition and disposal of unauthorised materials to cease. Reinspection the next day found that the abatement notices were being complied with at the time of inspection. A further inspection was undertaken under search warrant to obtain further evidence. Te Ataiawa were advised of the incident. Further enforcement action is being considered.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|--|---------------------------------------|---|------------------------|---|-----------------------------|
| 21 Jul 2020 <u>Update</u> | 3301-21-055 IN/40178 | Groundwater - Colson Road Landfill - New Plymouth | TRC Staff Compliance Monitoring | New Plymouth District Council (9565) | R2/4621-1 R2/4619-1 | EAC-23544 - Abatement Notice EAC-23543 - Abatement Notice EAC-23457 - Explanation Requested - Letter | Investigation Continuing |

Comments: During analysis of data it was found that three groundwater monitoring bores were compromised and also that there were some changes in parameters that likely exceeded the maximum natural background variation that should be identified in the sites management plan, at the Colson Road Landfill in New Plymouth. A meeting was held with New Plymouth District Council (NPDC) staff, where it was confirmed that the groundwater bores were compromised. A report from an environment consultant confirmed that monitoring of the under liner drainage had shown that there were changes in a number of parameters that exceeded the maximum natural background variations. NPDC have undertaken further investigation and have confirmed that non-compliant discharges are occurring. Further investigation is being undertaken to determine the best locations for the ground water monitoring bores and to establish trigger values for the determination of when environmental effects are occurring. Abatement notices have been issued requiring works to be undertaken to ensure consent compliance.

| 31 Jul 2020 <u>Update</u> | 3301-21-034 IN/40151 | Odour - Swansea Road, Stratford | Complaint | Interdrill (71978) | EAC-23494 - Explanation Requested - Letter | Investigation Continuing |
|------------------------------|-------------------------|------------------------------------|-----------|--------------------|---|-----------------------------|
| | | | | | | |

Comments: A complaint was received concerning odour in the Swansea Road area at Stratford. Investigation found that odour was emanating from a fire on an industrial site on Swansea Road. Some unauthorised materials were being burnt on the fire. The fire was extinguished at the time of inspection. Enforcement action is being considered.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|--|-----------|--|-------------------|---------------------------------|-----------------------------|
| 03 Aug 2020 <u>Update</u> | 3301-21-057 IN/40195 | Discoloured wetland - East Road, Toko | Complaint | Burgess Crowley Partnership (67500) | R2/7963-1 | EAC-23476 - Abatement Notice | Investigation Continuing |

Comments: A complaint was received regarding water in a wetland being discoloured at a property on East Road, Toko. Investigation found the water was discoloured. The discoloration was traced to a quarry site on East Road. Samples were taken. Analysis of samples found that suspended solids were above allowable resource consent conditions limits. An abatement notice was issued requiring works to be undertaken to ensure compliance. Reinspection found that significant works had been undertaken to comply with the abatement notice. Further enforcement action is being considered.

| 18 May 2020 | 3301-20-477 | Black smoke - Inland North | Complaint | Darryl Horgan (71455) | EAC-23498 - Infringement No Further Action |
|-------------|-------------|----------------------------|-----------|-----------------------|--|
| Update | IN/39723 | Road, Tikorangi | | | Notice (\$300) |

Comments: A complaint was received regarding black smoke discharging across the Pohokura/Methanex sites from the Inland North Road, Tikorangi area. Investigation found that a fire was burning at a property on Inland North Road. Some unauthorised materials were present on the fire, including 20 litre plastic chemical containers, car parts and a rubber mat, in contravention of rules in the Regional Air Quality Plan for Taranaki. The fire burnt out during the inspection.

| 26 May 2020 <u>Update</u> | 3301-21-054 IN/40172 | Unauthorised culvert - Puke Road, Uruti | TRC Staff Compliance Monitoring | New Plymouth District Council (9565) | EAC-23568 - Abatement Notice | No Further Action At This Stage/Costs |
|------------------------------|-------------------------|--|---------------------------------------|---|---------------------------------|---|
| | | | | | | Recovered |

Comments: During unrelated monitoring it was found that a culvert had been installed under Puke Road at Uruti in contravention of rules in the Regional Fresh Water Plan for Taranaki. An abatement notice was issued requiring works to be undertaken to ensure compliance with Rule 52 of the Regional Fresh Water Plan for Taranaki. Reinspection will be undertaken after 25 January 2021.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|-------------------------------------|-----------|------------------------------|-------------------|--|-------------------|
| 13 Jun 2020 <u>Update</u> | 3301-20-513 IN/39922 | Black smoke - South Road, Hawera | Complaint | Bruce Commerer (71670) | | EAC-23500 - Infringement Notice (\$300) | No Further Action |

Comments: A complaint was received concerning black smoke from small rubbish fire at rear of building on South Road, Hawera. Investigation found that unauthorised materials were being burnt on site. Photographs were taken.

| 03 Aug 2020 <u>Update</u> | 3301-21-044 IN/40162 | Sewage discharge - High Street, Eltham | Complaint | Shayna Pemberton (72026) William Jane (69832) | EAC-23525 - Infringement Notice (\$750) | No Further Action |
|------------------------------|-------------------------|---|-----------|--|--|-------------------|
| | | | | | EAC-23462 - Abatement | |

Notice

Comments: A complaint was received concerning a sewage discharge into a paddock at High Street, Eltham. Investigation found that some sewage was ponding on the surface of a paddock in contravention of an abatement notice issued as a result of previous non-compliances. The property was in the process of being sold. The current owner (at that time) undertook to clean out the septic tank. A further inspection after the property had been sold found this had not been done. Further enforcement action is being considered against the previous owner. The new owner was spoken to about what is required and it was agreed that an abatement notice would be issued requiring compliance with rules in the Regional Fresh Water Plan for Taranaki. Reinspection found the abatement notice was being complied with.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|---------------------------------------|-----------|--------------------------------------|-------------------|--|-------------------|
| 04 Aug 2020 <u>Update</u> | 3301-21-036 IN/40147 | Odour - Young Street, New Plymouth | Complaint | Modern Day Miners Limited (71967) | | EAC-23449 - Explanation Requested - Letter EAC-23448 - Abatement Notice | No Further Action |

Comments: A complaint was received regarding odour in the Young Street area in New Plymouth. Investigation found that there was an objectionable chemical type odour in the area, which was traced to a neighbouring property where a Company was melting solder from computer mother boards with inadequate ventilation extraction. An abatement notice was issued requiring the works to cease. Reinspection found that the abatement notice was being complied with. A letter requesting explanation was sent. Reinspection found that the machinery on the site was no longer in use.

| 11 Aug 2020 <u>Update</u> | 3301-21-056 IN/40196 | Trees in stream - Tauwharenikau Road, Tuttawa | TRC Staff Notification | Powerco Limited (12931) Tricky Tree Specialist (33789) | EAC-23475 - Abatement Notice | No Further Action |
|------------------------------|-------------------------|--|---------------------------|--|---------------------------------|-------------------|
|------------------------------|-------------------------|--|---------------------------|--|---------------------------------|-------------------|

Comments: During unrelated monitoring it was found that some trees had been felled into and across a stream on a property at Tauwharenikau Road, Tututawa. Investigation found that a power company had engaged contractors to clear power lines and in the process trees had been dropped in and around the stream. An abatement notice was issued requiring the trees to be removed. Reinspection found that this was done.
| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|--|-----------|--|-------------------|---------------------------------|-----------------------------|
| 07 Aug 2020 | 3301-21-081 IN/40323 | Rubbish near stream - Everett Road, Inglewood | Complaint | Paul Hitchcock (23839) Vertical Horizon Camp Trust (27436) | | EAC-23510 - Abatement Notice | Investigation Continuing |

Comments: A complaint was received concerning rubbish dumped adjacent to the Mangatiti Stream, Everett Road, Inglewood. Investigation found rubbish had been dumped and covered with soil within 25 metres of the stream. Soil had discharged into the stream causing discolouration and a build-up of soil within the stream bed. During the inspection it was also found that a rock dam had been constructed for stock access which appeared to restrict the flow of water and not allow the passage of fish. An abatement notice was issued requiring works to be undertaken to comply with rules in the Regional Fresh Water Plan for Taranaki. Reinspection will be undertaken after 7 October 2020.

| 15 Aug 2020 | 3301-21-065 | Smokey fire - Manutahi Road, | Complaint | M Hareb Excavating | Investigation |
|-------------|-------------|------------------------------|-----------|--------------------|---------------|
| | IN/40224 | Bell Block | | Limited (32118) | Continuing |

Comments: A complaint was received concerning black and odourous smoke coming from an industrial site on Manutahi Road, Bell Block. Investigation found that burning of unauthorised materials was occurring on the site. The area is utilised as a service facility for the oil/gas industry. A plume of thick black smoke was able to be seen from some distance away. Investigation found that a large skip bin had been dug into the ground at the rear of the site and materials that were being burnt included plastics, building materials and a mattress. The site owner admitted to lighting the fire and that it was a common occurrence on site. He was advised that burning was prohibited. The fire was extinguished at the time of inspection. Enforcement order is being considered.

| 17 Aug 2020 | 3301-20-067 | Smokey fire - Tawhiti Road, | Complaint | Ian Barr & Cathryn Finch | Investigation |
|-------------|-------------|-----------------------------|-----------|--------------------------|---------------|
| | IN/40228 | Hawera | | (52563) | Continuing |

Comments: A complaint was received concerning smoke from a fire on Tawhiti Road, Hawera. Investigation found that a vegetation pile from recent forestry activities had been set alight and caused a large amount smoke to discharge beyond the boundary of the site, over part of the Hawera township. It was also found that there was also other vegetation/debris within a small stream that was running through the area which had caught on fire. The landowners were advised of rules in the regional plans. Enforcement action is being considered.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | |
|--|-------------------------|---|---------------------------------------|---|-------------------|---------------------------------|-----------------------------|--|
| 01 Sep 2020 | 330121-106 IN/40296 | Offal discharge - State Highway 3, Midhirst | Self-Notification | Jackson Transport (21215) | | | Investigation Continuing | |
| Comments: Notification was received concerning waste offal product from a truck, destined for a waste processing plant, which had discharged onto State Highway 3 between Midhirst and Tariki. Investigation found that the discharge had occurred due to a damaged spring latch on the tailgate of the truck, which the truck driver had failed to rectify. A contractor was engaged to undertake clean-up works. Enforcement action is being considered. | | | | | | | | |
| 02 Sep 2020 | 3301-21-085 IN/40392 | Forestry harvesting non- notification - Uruti Valley Road, Uruti | TRC Staff Notification | Richard Dreaver (37034) | | | Investigation Continuing | |
| | he site operator | monitoring it was found that some t advised that the notification had be | | | | | | |
| 04 Sep 2020 | 3301-21-092 IN/40327 | Rubbish near stream - Auroa Road, Otakeho | TRC Staff Compliance Monitoring | Furness Trusts Partnership (20349) Michelle Furness (51863) | R2/2973-2 | EAC-23511 - Abatement Notice | Investigation Continuing | |

Comments: During unrelated monitoring it was found that rubbish had been dumped within 25 metres of the Kuporaho Stream, Auroa Road, Otakeho. The landowner confirmed all rubbish had been generated on the property. An abatement notice was issued requiring works to be undertaken to ensure compliance with Rule 30 of the Regional Fresh Water Plan for Taranaki. Reinspection will be undertaken after 21 October 2020.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|---|---------------------------|--|-------------------|--|-----------------------------|
| 08 Sep 2020 | 3301-21-095 IN/40372 | Land drainage - Ahipaipa Road, Okaiawa | TRC Staff Notification | Craig Wilson (69791) Leroy Nelley (69188) | | EAC-23536 - Explanation Requested - Letter EAC-23534 - Abatement Notice | Investigation Continuing |

Comments: During unrelated monitoring it was found that some unconsented earthworks were being undertaken near a wetland area on a property at Ahipaipa Road, Okaiawa. An abatement notice was issued requiring reinstatement works to be undertaken to ensure compliance with the Resource Management (National Environmental Standard for Freshwater) Regulations 2020. Reinspection to be undertaken after 30 November 2020.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|---|-----------|---|-------------------|---|-----------------------------|
| 09 Sep 2020 | 3301-21-096 IN/40377 | Unconsented cleanfill - Ararata Road, Hawera | Complaint | Anthony Bourke (72141) AP Bourke Farm Trust (25221) Daryll Anderson (72149) Leigh Williamson (55297) Louise Hofmann (72142) Sybrandy AB & DM Contracting Limited (13363) | | EAC-23558 - Explanation Requested - Letter EAC-23557 - Explanation Requested - Letter EAC-23556 - Explanation Requested - Letter EAC-23555 - Explanation Requested - Letter EAC-23554 - Explanation Requested - Letter EAC-23552 - Explanation Requested - Letter EAC-23552 - Explanation Requested - Letter EAC-23551 - Explanation Requested - Letter EAC-23551 - Explanation Requested - Letter EAC-23540 - Abatement Notice EAC-23539 - Abatement Notice | Investigation Continuing |

Comments: A complaint was received concerning an unconsented cleanfill on a property at Ararata Road, Hawera. Investigation found a number of companies and individuals had been depositing materials on a dairy farm property. The majority of materials were inert and allowed, however there was a significant amount of unauthorised materials such as, treated timber, steel, building materials, plumbing and electrical products, flooring and concrete with re-bar etc. Abatement notices were issued requiring further dumping of unauthorised material to cease and for Rule 44 of the Regional Fresh Water Plan for Taranaki to be complied with. Further enforcement action is being considered.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | |
|--|--|--|---------------------------|---|-------------------|---------------------------------|-----------------------------|--|
| 17 Sep 2020 | 330121-099 IN/40399 | Smoke - Cross/Kelly Roads, Lepperton | Complaint | Amanda Goble (70469) Brian Goble (70468) | | EAC-23535 - Abatement Notice | Investigation Continuing | |
| Comments: A complaint was received concerning smoke discharging from a fire on a neighbouring property at the corner of Cross Road and Kelly Road, Lepperton. Investigation found that there was a tyre being burnt on top of a pile of smouldering calf bedding. Objectionable smoke was discharging beyond the boundary of the property. An abatement notice was issued requiring compliance with Rules 31 and 61 of the Regional Air Quality Plan for Taranaki. Further enforcement action is being considered. | | | | | | | | |
| 20 Sep 2020 | 3301-21-104 IN/40442 | Industrial burning - Kerry Lane, Hawera | TRC Staff Notification | Agtrans Ltd (68619) | | | Investigation Continuing | |
| old trailer, inclu | uding oil contain | monitoring it was found that unauth ers, fiberglass truck parts, roofing in prohibited. Enforcement action is be | on, IBCs and buildi | | | | • | |
| 22 Sep 2020 | 3301-21-105 IN/40419 | Milk in Matanehunehu Stream - Mid Puniho Road, Okato Puniho | Complaint | Pinewood Dairy Limited (35681) | R2/0457- 4.0 | | Investigation Continuing | |
| where the milk | Comments: A complaint was received concerning milk in the Matanehunehu Stream, at Puniho Road, Okato. Investigation found that milked had discharged from a vat on a farm where the milker had forgotten to close a valve. All of the morning's milk had gone directly down the drain. This would have usually gone directly to the effluent ponds but as a esult of the stormwater diversion being changed over, all the milk discharged directly to the stream. On speaking with the farm owner it was found that there were some health | | | | | | | |

issues with the farm worker. Further enforcement action is being considered.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|--|-----------|--|-------------------|--|---|
| 15 Aug 2020 | 3301-20-063 IN/40222 | Smokey fire - Tukapa Street, New Plymouth | Complaint | Smudgy Developments (56784) | | | No Further Action |
| on the site, wh | ich was also a c | received concerning a smokey fire a onsented cleanfill site. A minimal a al Air Quality Plan for Taranaki. | | | | • • • | |
| 20 Aug 2020 | 3301-21-071 IN/40232 | DAF Odour - Collingwood Street, Eltham | Complaint | Fonterra Co-Operative Group Limited (28692) Intergroup Limited (53424) | | EAC-23529 - Infringement Notice (\$1000) EAC-23528 - Infringement Notice (\$1000) EAC-23467 - Explanation Requested - Letter EAC-23466 - Explanation Requested - Letter | No Further Action/Costs Recovered |
| | • | received regarding an odour from th ance activities being undertaken on | | . | , Eltham. Inve | stigation found that an objecti | onable DAF odour |

| 20 Aug 2020 | 3301-20-072 | Oil discharge - truck accident - | Self-Notification | Cameron Broughton | No Further Action |
|-------------|-------------|----------------------------------|-------------------|-------------------|-------------------|
| | IN/40250 | Tariki | | (72076) | |

Comments: Notification was received from Fire and Emergency New Zealand concerning a discharge of oil from a truck accident on State Highway 3 near Inglewood. Investigation found that a truck transporting waste oil filters had overturned into a roadside drain, with some oil discharging into the drain. Trained oil spill responders attended the site and deployed booms and sorbant materials to contain and recover all of the oil. No oil reached any waterbody.

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------------------------|---|---|--|---|-------------------|--|---|
| 22 Aug 2020 | 3301-21-073 IN/40249 | Discoloured stream - Ariel Street, Stratford | Complaint | Unsourced (9768) | | | No Further Action |
| slightly milky ir | n colour. Despite | received concerning discolouration extensive investigation upstream, eared during the inspection. | | | | | |
| 30 Aug 2020 | 3301-21082 IN/40420 | Dairy effluent - Taikatu Road, Auroa | Complaint | Anthony Muller (72151) | R2/2657- 3.0 | | No Further Action/Costs Recovered |
| Investigation for advised that he | ound that while t e had set the irri | received regarding dairy effluent be here was dairy effluent on the roads gator that morning for a two hour pe lent onto the roadside. There is no | side grass verge, th eriod and then had f | e irrigator was not operational forgotten to turn it off. He turne | at the time of | inspection. The farm owner w | vas spoken to who |
| 02 Sep 2020 | 3301-083 IN/40421 | Sewage discharge - Bell Street, New Plymouth | Complaint | New Plymouth District Council (9565) | | No Enforcement Action - Statutory defence | No Further Action |
| | ain and the disch | as received concerning a sewage o arge was stopped immediately. The | | | | | |

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | | |
|------------------|--|---|--------------------|---|-------------------|--|-------------------|--|--|
| 03 Sep 2020 | 3301-21-088 IN/40436 | Sewage discharge - Cracroft Street, Waitara | Self-Notification | New Plymouth District Council (9565) | | No Enforcement Action - Statutory defence | No Further Action | | |
| | Comments: Self-notification was received concerning a sewage discharge to stormwater at Waitara Central School, Cracroft Street, Waitara. Investigation found that the lischarge was due to a blocked drain. The drain was unblocked immediately and signs were put out. The contingency plan was followed. | | | | | | | | |
| 05 Sep 2020 | 3301-21-090 IN/40317 | Discoloured Stream - Rimu Street, New Plymouth | Complaint | Unsourced (9768) | | | No Further Action | | |
| most likely cau | | received concerning a discoloured s shings. Despite extensive investiga am. | | | | | | | |
| 07 Sep 2020 | 3301-21-091 IN/40319 | Green Stream - Beaconsfield Road, Midhurst | Complaint | Lewis Schumacher (72093) | R2/3230-1 | No Enforcement Action - Statutory defence | No Further Action | | |
| Investigation of | f upstream prop | received concerning a 'green' strea erties found that the outlet of a sam ed tributary. The blockage was remo | d trap was blocked | | | | | | |

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | | |
|---|---|---|---------------------------------------|--|-------------------|--|-------------------|--|--|
| 13 Sep 2020 | 330121-094 IN/40370 | Milk discharge - Tanker accident - Makowhai Road, Hawera | Self-Notification | Fonterra Limited (50606) | | No Enforcement Action - Statutory defence | No Further Action | | |
| Comments: Notification was received from Fonterra, advising that a milk tanker had overturned on a property at Makowhai Road, Hawera, causing milk to discharge to a stream. Investigation found that a milk tanker, being driven by a trainee driver and having a full load of milk, had overturned while moving over a narrow culvert. It was estimated that approximately 200-300 litres of milk discharged into a large wetland/unnamed tributary. The tributary had been dammed many years ago, creating a 650 m wetland/lake. No actions were taken to clean up the milk as it was decided it was best for the environment for natural remediation to occur. | | | | | | | | | |
| 15 Sep 2020 | 3301-21-098 IN/40418 | Dead calves drain - Kahui Road, Rahotu | TRC Staff Compliance Monitoring | Mark Campbell & Dianne Alice Lusk (10862) | R2/2651- 3.0 | No Enforcement Action - Statutory defence | No Further Action | | |
| | - | monitoring it was found that there w nd was unaware the calves were in | | | - | he farm property at Kahui Ro | ad, Rahotu. The | | |
| 18 Sep 2020 | 3301-21-101 IN/40413 | Backyard burning - Kamahi Road, Hawera | Complaint | Edward Prime (72147) | | | No Further Action | | |
| that the elderly | comments: A complaint was received concerning burning in a neighbouring property at Kamahi Road, Hawera. Investigation found that a make shift furnace had been erected so nat the elderly male occupant could burn some tree cuttings. He was not present at the time of inspection but his daughter was spoken to and advised that he is not allowed to ave a fire in his backyard. She advised that her father was unaware of the rules but that she would ensure he was fully aware that he could not burn. | | | | | | | | |

| Incident Date | Job Number / IRIS ID | Incident Type | Source | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------|-------------------------|----------------------------|-----------|------------------------------|-------------------|--------------|-------------------|
| 21 Sep 2020 | 3301-21-107 IN/40441 | Dead sheep - Waitara Beach | Complaint | Unsourced (9768) | | | No Further Action |

Comments: A complaint was received concerning dead sheep on Waitara Beach. Investigation found that there was a bloated adult sheep with no legs located on the sand in the Waitara River Estuary at the end of Jackson Street and East Quay. The owner could not be traced. New Plymouth District Council were advised and undertook removal of the carcass.

Updates of Compliance Monitoring - Non-compliances from previous agendas

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|--------------------------------|----------------------|---------------------------|-------------------|--------------|------------------------------------|
| 05 Sep 2018 <u>Update</u> | 332119-044 ENF-21673 | Compliance Monitoring Insp. | Non-compliance | Tania Jenna Brown (16070) | R2/5473-1 | | No Further Action At This Stage |

Comments: During a consent renewal inspection it was found that a weir was not operating within resource consent conditions at State Highway 45, Tataraimaka. Fish passage had not been maintained as required by resource consent conditions. Several meetings were held with the consent holder and affected parties. An agreement has been reached by the parties that works will be undertaken to ensure that consent conditions are complied with. Access to the site has now become an issue.

| 10 Jul 2019 <u>Update</u> | 332120-024 ENF-22082 | Compliance Monitoring Insp. | Non-compliance | Bland & Jackson Surveyors Ltd (10034) Settlers Bush Trustees Limited | R2/10227- 1.0 | EAC-23470 - Infringement Notice (\$750) EAC-22798 - Abatement | Investigation Continuing |
|------------------------------|-------------------------|--------------------------------|----------------|--|------------------|---|-----------------------------|
| | | | | (52723) | | Notice | |

Comments: During routine monitoring it was found that a dam site on a property at a subdivision on Honeyfield Drive, New Plymouth was not complying with resource consent conditions. An abatement notice was issued requiring resource consent conditions to be complied with. Reinspection found that the abatement notice was not being complied with at the time of inspection. A letter of explanation has been requested. Further enforcement action is being considered.

| 19 Jun 2020 332120-163 Compliance Significant non- Herd Properties Limited (70488) <u>Update</u> ENF-22571 Monitoring Insp. compliance | R2/10808- 1.0 | EAC-23426 - Abatement Notice EAC-23501 - Infringement Notice (\$750) EAC-23425 - Explanation Requested - Letter | No Further Action/Costs Recovered |
|---|------------------|--|---|
|---|------------------|--|---|

Comments: During routine monitoring it was found that stormwater from disturbed areas was not directed through silt and sediment controls at a development site at Pohutukawa Place, Bell Block. Significant amounts of silt and sediment laden stormwater was discharging off site and into the stormwater network. Analysis of samples taken during the inspection found that suspended solid levels were above allowable limits in resource consent conditions.

Updates of Compliance Monitoring - Non-compliances from previous agendas

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|----------------------|----------------------|-----------------------------|-------------------|---|---|
| 02 Jul 2020 <u>Update</u> | 332121-008 ENF-22606 | Annual Inspection | Non-compliance | The Tom Lance Trust (51397) | R2/3312-3.1 | EAC-23468 - Infringement Notice (\$750) EAC-23465 - Explanation Requested - Inspection Notice | No Further Action/Costs Recovered |

Comments: During routine monitoring it was found that water abstraction volume limits had been contravened on numerous occasions between 12 October 2019 and 1 May 2020, in contravention of Abatement Notice EAC-22773 issued as a result of previous non-compliances. Also it was found that no dip tube had been installed as instructed during previous monitoring. The dip tube is required before an automatic ground level recording device can be installed, which is also required by Abatement Notice EAC-22773.

| 07 Jul 2020 <u>Update</u> | 332121-001 ENF-22587 | Follow Up Inspection | Non-compliance | Schlumberger New Zealand Limited (51451) | R2/7591-1.2 | EAC-23486 - Infringement Notice (\$750) | No Further Action/Costs |
|------------------------------|-------------------------|-------------------------|----------------|---|-------------|--|----------------------------|
| opullo | | mspoodon | | Surrey Road Land Farm Limited (32728) | | EAC-23484 - Infringement Notice (\$750) | |

Comments: During a follow-up inspection It was found that a land farming site was not complying with resource consent conditions. The irrigation pit was discharging into an adjacent drain. A meeting was held with the site operators. They have undertaken mitigation measures to ensure consent compliance. Reinspection found that the site was compliant.

| 15 Jul 2020 <u>Update</u> | 332121-002 ENF-22580 | Annual Inspection | Significant non- compliance | St George By The Sea Limited (50987) | R2/1466-3 | EAC-23480 - Infringement Notice (\$750) EAC-23424 - Explanation Requested - Letter | No Further Action/Costs Recovered | |
|------------------------------|-------------------------|----------------------|--------------------------------|---|-----------|---|---|--|
|------------------------------|-------------------------|----------------------|--------------------------------|---|-----------|---|---|--|

Comments: During routine monitoring it was found that the farm dairy effluent disposal system was not operating within resource consent conditions. The sandtrap was blocked and overflowing to water. The sump was full and overflowing to land. The issues were rectified at the time of inspection.

Updates of Compliance Monitoring - Non-compliances from previous agendas

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|----------------------|----------------------|-----------------------------|-------------------|--|---|
| 20 Jul 2020 <u>Update</u> | 332121-005 ENF-22594 | Annual Inspection | Non-compliance | Ample Group Limited (52845) | R2/5176-2.0 | EAC-23524 - Infringement Notice (\$500) EAC-23491 - Abatement Notice EAC-23439 - Explanation Requested - Inspection Notice | No Further Action/Costs Recovered |

Comments: During routine monitoring it was found that the water abstraction data logger was not working and no abstraction records were available at a property at Mountain Road, Stratford. A letter of explanation was received.

| 30 Jul 2020 <u>Update</u> | 332121-004 ENF-22590 | Office Assessment | Non-compliance | Burgess Crowley Partnership (67500) | R2/7964-1.1 | Notice (\$500) EAC-23436 - Abatement | No Further Action/Costs Recovered |
|------------------------------|-------------------------|----------------------|----------------|-------------------------------------|-------------|---|---|
| | | | | | | Notice | |

Comments: During routine monitoring it was found that no data had been received for the 2018-2019 and 2019-2020 period and that there was no staff gauge located at a water abstraction site at East Road, Stratford. An abatement notice was issued requiring resource consent conditions to be complied with at all times. Compliance with the abatement notice will be ascertained during the next monitoring period.

| 12 Aug 2020 | 332121-006 | Compliance | Non-compliance | Forgotten Farms Limited (68504) | R2/10710- | EAC-23459 - Abatement | No Further |
|---------------|------------|------------------|----------------|---------------------------------|-----------|-----------------------|--------------|
| <u>Update</u> | ENF-22603 | Monitoring Insp. | | Growing Gold Limited (72011) | 1.1 | Notice | Action/Costs |
| | | | | | | | Recovered |

Comments: During routine monitoring it was found that there were insufficient sediment controls installed and sediment was entering water at a forest harvesting site at Arnold Road, Pohokura. An abatement notice was issued requiring works to be undertaken to ensure compliance with resource consent conditions. Reinspection found that the abatement notice was being complied with at the time of inspection.

<u>Updates of Compliance Monitoring - Non-compliances</u> from previous agendas

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|------------------------------|-------------------------|----------------------|----------------------|--|-------------------|---------------------------------|--|
| 12 Aug 2020 <u>Update</u> | 332121-009 ENF-22619 | Annual Inspection | Non-compliance | KL & DE Harvey Family Trusts Partnership (3499) | R2/2309-3.0 | EAC-23481 - Abatement Notice | No Further Action At This Stage/Costs Recovered |

Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions on Kina Road, Rahotu. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 1 December 2021.

| Inspection Date | Job Number IRIS ID | Inspection Type | Complianc e Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|--|--------------------------------|----------------------------------|---|--------------------------------------|---------------------------------|---|
| 06 Jul 2020 | 332121-007 ENF-22609 | Compliance Monitoring Insp. | Non-compliance | Peter John Colman (70249) | R2/10798- 1.0 R2/10798- 1.1 | | No Further Action/Costs Recovered |
| | Ouring routine mo aditions and this | | nd that a culvert had | been installed in contravention of reso | urce consent co | nditions. The consent holder a | applied for a change |
| 18 Aug 2020 | 332121-013 ENF-22613 | Annual Inspection | Non-compliance | Tynedale Farms (12587) | R2/1594-3 | EAC-23472 - Abatement Notice | No Further Action/Costs Recovered |
| Commonto: D |)uring analysis o | f samples (26 Augu | | ng the annual dairy inspection round (1 ditions at Manihi Road, Rahotu. An aba | | | |
| oond disposal | | | | e consent conditions. Reinspection fou | | | |

undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 1 December 2020.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------------------|-------------------------|--------------------------------|----------------------|---|-------------------|---|--|
| 19 Aug 2020 | 332121-011 ENF-22611 | Compliance Monitoring Insp. | Non-compliance | TPJ Partnership (12834) | R2/10202- 1.0 | EAC-23495 - Explanation Requested - Letter | Investigation Continuing |
| Comments: D is being consid | - | onitoring unauthoris | ed materials were f | ound in a cleanfill at Rainie Road, Hawe | ra. A letter requ | esting explanation was sent. | Enforcement action |
| 20 Aug 2020 | 332121-017 ENF-22623 | Annual Inspection | Non-compliance | Mr SJ & JM Andrews (72085) | R2/2408-2 | EAC-23518 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
| oxidation pond | l disposal system | n was not operating | within resource co | during the annual dairy inspection round nsent conditions at Upland Road, Egmo liance with resource consent conditions. | nt Village. An at | atement notice was issued re | equiring works to be |
| 20 Aug 2020 | 332121-042 ENF-22675 | Annual Inspection | Non-compliance | Catalina Farms (3941) | R2/3771-2 | | Investigation Continuing |
| | | | | luring the annual dairy inspection round nsent conditions at De Havilland Drive a | | | • |

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|--------------------------------|-----------------------------|-------------------|---|-----------------------------|
| 20 Aug 2020 | 332121-024 ENF-22634 | Annual Inspection | Significant non- compliance | Grant Allen Limited (20504) | R2/2348-2 | EAC-23507 - Abatement Notice EAC-23508 - Explanation Requested - Letter EAC-23506 - Abatement Notice | Investigation Continuing |

Comments: During analysis of samples (2 September 2020), taken during the annual dairy inspection round (20 August 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions at Ngatimaru Road, Tikorangi. Works were immediately undertaken to the effluent disposal system to ensure compliance. A letter requesting explanation was sent. Enforcement action is being considered.

| 24 Aug 2020 | 332121-027 ENF-22656 | Annual Inspection | Non-compliance | DJ Harvey Family Trusts Partnership (69531) | R2/1608-4.0 | EAC-23538 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
|-------------|-------------------------|----------------------|----------------|--|-------------|---------------------------------|--|
| Comments: D | Ouring analysis o | of samples (21 Sept | | during the annual dairy inspection round | · · | | |

Comments: During analysis of samples (21 September 2020), taken during the annual dairy inspection round (24 August 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions at Parihaka Road, Pungarehu. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 30 November 2020.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|--|--|--|---|-------------------|--|--|
| 24 Aug 2020 | 332121-018 ENF-22637 | Compliance Monitoring Insp. | Non-compliance | Greymouth Facilities Limited (30688) | R2/9868-1.1 | EAC-23509 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
| at an industria | I site on Corbett | | abatement notice | ing it was found that consent conditions was issued requiring works to be under | | • | • • |
| 24 Aug 2020 | 332121-043 ENF-22674 | Compliance Monitoring Insp. | Non-compliance | Symons Property Developments Limited (34584) | R2/7805-1 | No Enforcement Action - Statutory defence | No Further Action |
| solids, at an ir | idustrial site on (as per the design | Connett Road, Bell I n from the consultar | Block. However, aften t, however this was | ing it was found that consent conditions er a previous non-compliance a consulta not working. The Company could not ha iring further routine monitoring. | ant had been co | ntracted to remedy the issue. | A system had been |
| be undertaker | | | | | | | |

| Inspection Date | Job Number IRIS ID | Inspection Type | Complianc e Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-----------------------|--------------------|----------------------------------|--------------------------------|-------------------|-----------------------|----------------|
| 24 Aug 2020 | 332121-014 | Annual | Significant non- | Wayne Bruce & Christine Louise | R2/10310- | EAC-23474 - Abatement | Investigation |
| | ENF-22615 | Inspection | compliance | Foreman (52343) | 1.1 | Notice | Continuing |

Comments: During the annual dairy inspection round it was found that the dairy effluent disposal system was not in compliance with resource consent conditions. An abatement notice was issued requiring works to be undertaken to ensure compliance with resource consent conditions. Reinspection will be undertaken after 20 December 2020. Further enforcement action is being considered.

| 24 Aug 2020 | 332121-022 ENF-22643 | Annual Inspection | Significant non- compliance | Steven John & Susan Helen Lye (11374) | R2/0533-3.0 | EAC-23516 - Abatement Notice EAC-23517 - Abatement Notice EAC-23515 - Explanation Requested - Letter | Investigation Continuing |
|-------------|-------------------------|----------------------|--------------------------------|--|-------------|---|-----------------------------|
|-------------|-------------------------|----------------------|--------------------------------|--|-------------|---|-----------------------------|

Comments: During analysis of samples (14 September 2020), taken during the annual dairy inspection round (24 August 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions at Ngatimaru Road, Tikorangi. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection found that the abatement notices were being complied with. Further enforcement action is being considered.

| 25 Aug 2020 | 332121-047 | Compliance | Significant non- | Port Taranaki Limited (26226) | R2/0197-2.1 | Investigation |
|-------------|------------|------------------|------------------|-------------------------------|-------------|---------------|
| | ENF-22677 | Monitoring Insp. | compliance | | | Continuing |

Comments: During analysis of samples taken during routine monitoring it was found that resource consent conditions were not being complied with, in relation to high suspended solids, and also in contravention of Abatement Notice EAC-22662, issued as a result of a previous non-compliance, at the Port, New Plymouth. A meeting was held with the Company who outlined a number of improvements to be undertaken to ensure compliance. Enforcement action is being considered.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|----------------------|--|-------------------|--------------|---|
| 26 Aug 2020 | 332121-040 ENF-22669 | Annual Inspection | Non-compliance | SJ & JL Fevre Trusts Partnership (23156) Stephen & Jenny Fevre (10729) | R2/1132-3 | | No Further Action/Costs Recovered |

Comments: During analysis of samples (14 September 2020), taken during the annual dairy inspection round (26 August 2020), it was found that the farm dairy effluent disposal system was not operating within resource consent conditions and was also in contravention of Abatement Notice EAC-21292 issued as a result of a previous non-compliance at Auroa Road, Manaia. The consent holder is in the process of installing a land based dairy effluent disposal system.

| 27 Aug 2020 332121 ENF-22 | | Significant non- compliance | D & M Hastie Family Trust No 1 & No 2 (14974) Mr GA Hastie (11007) | R2/3586-2 | EAC-23562 - Explanation Requested - Letter | Investigation Continuing | |
|------------------------------|--|--------------------------------|--|-----------|---|-----------------------------|--|
|------------------------------|--|--------------------------------|--|-----------|---|-----------------------------|--|

Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions and was also in contravention of Abatement Notice EAC-22221 issued as a result of a previous non-compliance at Rama Road, Kaupokonui. A letter requesting explanation has been sent. Enforcement action is being considered.

| 28 Aug 2020 | 332121-025 ENF-22649 | Annual Inspection | Significant non- compliance | Whenuakura Farm Limited (37558) | R2/3285-2 | EAC-23541 - Explanation Requested - Letter | Investigation Continuing | |
|-------------|-------------------------|----------------------|--------------------------------|---------------------------------|-----------|---|-----------------------------|--|
|-------------|-------------------------|----------------------|--------------------------------|---------------------------------|-----------|---|-----------------------------|--|

Comments: During analysis of samples (15 September 2020), taken during the annual dairy inspection round (28 August 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions and was also in contravention of Abatement Notice EAC-22197 issued as a result of a previous non-compliance at Hukatere Road, Whenuakura. A letter requesting explanation was sent. Enforcement action is being considered.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|--------------------------------|---|-------------------|--|-----------------------------|
| 28 Aug 2020 | 332121-035 ENF-22647 | Annual Inspection | Significant non- compliance | Bellevue Farming (2007) Limited (30733) | R2/0971-3 | EAC-23521 - Abatement Notice EAC-23530 - Abatement Notice | Investigation Continuing |
| oxidation pond | l disposal system | n was not operating | within resource con | during the annual dairy inspection round nsent conditions at Kaharoa Road, Pate Reinspection will be undertaken after 3 | a. Abatement no | tices were issued requiring the | ne discharge to |
| 28 Aug 2020 | 332121-041 ENF-22672 | Annual Inspection | Significant non- compliance | Kaupok Limited Partnership (52170) | R2/0725-3.0 | | Investigation Continuing |
| | · · | | | during the annual dairy inspection round nsent conditions at Manaia Road, Manai | | | n dairy effluent |
| 31 Aug 2020 | 332121-015 | Annual | Non-compliance | Nigel Wayne & Denise Mary King | R2/4276-2.1 | EAC-23499 - Abatement | No Further Action |

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|--------------------------------|---|-------------------|---|--|
| 31 Aug 2020 | 332121-036 ENF-22665 | Annual Inspection | Non-compliance | lan Honeyfield Trust (37545) | R2/1129-2 | EAC-23565 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
| oxidation pond | l disposal systen | n was not operating | within resource co | during the annual dairy inspection roun nsent conditions at Patea Road, Whenu aken after 2 November 2020. | | | · · |
| 31 Aug 2020 | 332121-028 ENF-22658 | Annual Inspection | Significant non- compliance | Kokako Road Limited (31856) | R2/4877-2 | EAC-23542 - Explanation Requested - Letter | Investigation Continuing |
| oxidation pond | l disposal system | n was not operating | within resource con | during the annual dairy inspection roun nsent conditions and was also in contra ing explanation was sent. Enforcement | vention of Abate | ment Notice EAC-21349 issu | |
| | | | | | | | |

Comments: During analysis of samples (22 September 2020), taken during the annual dairy inspection round (31 August 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions at Mangawhero Road, Kaponga. An abatement notice was issued requiring works to be undertaken to ensure consent compliance. Reinspection to be undertaken after 30 November 2020.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | |
|---|-------------------------|--------------------------------|--------------------------------|--|-------------------|---------------------------------|--|--|
| 31 Aug 2020 | 332121-026 ENF-22655 | Annual Inspection | Non-compliance | Daniel & Beryl Meyer (9386) Meyer DR Trust & Est B A Meyer (3039) | R2/1323-3 | EAC-23537 - Abatement Notice | No Further Action At This Stage/Costs Recovered | |
| oxidation pond | disposal system | n was not operating | within resource co | during the annual dairy inspection round nsent conditions at Kokiri Road, Manaia. liance with resource consent conditions. | An abatement | notice was issued requiring w | orks to be | |
| 01 Sep 2020 | 332121-023 ENF-22636 | Compliance Monitoring Insp. | Non-compliance | Firth Industries Limited (10053) | R2/0392-4.0 | | Investigation Continuing | |
| Comments: During analysis of samples taken during routine monitoring it was found that resource consent conditions were being contravened, in relation to high suspended solids. This was also in contravention of Abatement Notice EAC-22917 issued as a result of a previous non-compliance. As this is a repeated non-compliance the Company advised that they would clean out the settling ponds and cease the discharge until a new system is in place, around 21 September 2020. Compliance will be ascertained during routine monitoring. Further enforcement action is being considered. | | | | | | | | |
| 02 Sep 2020 | 332121-039 ENF-22670 | Annual Inspection | Significant non- compliance | Kohinoor Farms Limited (20596) | R2/1343-3 | EAC-23574 - Abatement Notice | Investigation Continuing | |
| | | | | during the annual dairy inspection round nsent conditions at Kohi Road, Waverley | | | arm dairy effluent | |

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation | |
|--|-------------------------|----------------------|--------------------------------|--|-------------------|--|--|--|
| 02 Sep 2020 | 332121-016 ENF-22624 | Annual Inspection | Non-compliance | Holmeshaw Trust Limited (20024) | R2/2236-3.0 | EAC-23497 - Abatement Notice | No Further Action At This Stage/Costs Recovered | |
| Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions on Oeo Road, Aurora. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 1 September 2021. Substantial works will be required, and the consent holder has undertaken to ensure consent compliance during this period. | | | | | | | | |
| 02 Sep 2020 | 332121-038 ENF-22663 | Annual Inspection | Non-compliance | Ian Alistair & Rosalie Janet Finer (1623) | R2/0841-3.1 | EAC-23563 - Abatement Notice | No Further Action At This Stage/Costs Recovered | |
| Comments: During analysis of samples (23 September 2020), taken during the annual dairy inspection round (2 September 2020), it was found that the farm dairy effluent oxidation pond disposal system was not operating within resource consent conditions at Inland North Road, Tikorangi. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 16 October 2020. | | | | | | | | |
| 02 Sep 2020 | 332121-021 ENF-22644 | Office Assessment | Significant non- compliance | Ample Group Limited (52845) | R2/7662-1 | EAC-23523 - Infringement Notice (\$750) | No Further Action/Costs Recovered | |

Comments: During analysis of data on 2 September 2020 it was found that allowable limits for wastewater discharge had been contravened between 4-30 June 2020, in contravention of resource consent conditions and Abatement Notice EAC-22966, which was issued as a result of a previous non-compliance.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|----------------------|---|-------------------|---------------------------------|--|
| 03 Sep 2020 | 332121-045 ENF-22671 | Annual Inspection | Non-compliance | Corrigan R & C Oaks Trusts Partnership (13438) Ross Corrigan (34266) | R2/5145-2 | EAC-23569 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
| oxidation pond | l disposal system | n was not operating | g within resource co | during the annual dairy inspection round nsent conditions at Nolan Road, Hawera liance with resource consent conditions | a. An abatement | notice was issued requiring v | works to be |
| 04 Sep 2020 | 332121-029 ENF-22659 | Annual Inspection | Non-compliance | Luttrell Trust Partnership (16921) | R2/0832-3 | EAC-23559 - Abatement Notice | No Further Action At This Stage/Costs Recovered |
| oxidation pond | l disposal system | n was not operating | g within resource co | during the annual dairy inspection round nsent conditions at Main South Road, O liance with resource consent conditions | eo. An abateme | nt notice was issued requiring | g works to be |
| 04 Sep 2020 | 332121-030 | Annual | Non-compliance | Kahurangi Trust (2139) Kelly Korau (67510) | R2/1887-3.0 | EAC-23561 - Abatement Notice | No Further Action At This |

oxidation pond disposal system was not operating within resource consent conditions at Auroa Road, Otakeho. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 30 November 2020.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|----------------------|---------------------------|-------------------|--------------|-------------------|
| 10 Sep 2020 | 332121-033 ENF-22664 | Annual Inspection | Non-compliance | Glencairn Trust (27255) | R2/3809-2 | | No Further Action |

Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions on Inaha Road, Hawera. It was found that effluent was being applied to land via a new land irrigation system, even though the consent only allowed the discharge to water via an oxidation pond treatment system. An application for early renewal of the resource consent was immediately lodged by the land owner to authorise the application to land. Environmental effects were far less likely because the discharge was to land rather than water.

| ENF-22641 Inspection Notice At Thi Stage | Further Action This ge/Costs sovered |
|--|---|
|--|---|

Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions on Lower Stuart Road, Eltham. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 23 October 2020.

| 10 Sep 2020 | 332121-032 | Compliance | Non-compliance | Silver Fern Farms Limited (30302) | R2/2260-3.1 | EAC-23560 - Explanation | Investigation |
|-------------|------------|------------------|----------------|-----------------------------------|-------------|-------------------------|---------------|
| | ENF-22660 | Monitoring Insp. | | | | Requested - Letter | Continuing |

Comments: During routine monitoring it was found that ponding of waste water was occurring in contravention of resource consent conditions at a meat processing plant in Waitotara. A letter requesting explanation has been sent.

| Inspection Date | Job Number IRIS ID | Inspection Type | Compliance Status | Alleged Responsible Party | Consent Number | Action Taken | Recommendation |
|--------------------|-------------------------|----------------------|----------------------|---|-------------------|---------------------------------|--|
| 22 Sep 2020 | 332121-044 ENF-22673 | Annual Inspection | Non-compliance | Andrew Paul Watkins (52191) Lugra Farm Partnership (56770) | R2/2014-3.0 | EAC-23570 - Abatement Notice | No Further Action At This Stage/Costs Recovered |

Comments: During the annual dairy inspection round it was found that the farm dairy effluent disposal system was not operating within resource consent conditions on Palmer Road, Kaponga. An abatement notice was issued requiring works to be undertaken to the farm dairy effluent disposal system to ensure compliance with resource consent conditions. Reinspection will be undertaken after 27 October 2020.

Consents and Regulatory Committee Public Excluded

In accordance with section 48(1) of the *Local Government Official Information and Meetings Act* 1987, <u>resolves</u> that the public is excluded from the following part of the proceedings of the Consents and Regulatory Committee Meeting on Tuesday 13 October 2020 for the following reason/s:

Item 6 - Public Excluded Minutes - 1 September 2020

THAT the public conduct of the whole or the relevant part of the proceedings of the meeting would be likely to result in the disclosure of information where the withholding of the information is necessary to protect information where the making available of the information would be likely unreasonably to prejudice the commercial position of the person who supplied or who is the subject of the information.

Agenda reports

Consents & Regulatory Committee October 2020

Item 3: Compliance monitoring reports

Osflo Fertiliser (850 KB) RKM Farms piggery (380 KB) NPDC Coastal Structures (2.3 MB) Ample Group Ltd (890 KB) Tawhiti Catchment (1.3 MB) Todd McKee Power Plant (890 KB) Regional Cleanfills (3.5 MB) Value Timber Ltd (540 KB) Greymouth Petroleum northern sites (800 KB) Cheal Production Station (660 KB) Cheal Deep Well Injection (2 MB) NZEC Deep Well Injection (1 MB) Westside Deep Well Injection (1.3 MB) Regional quarries - northern (4.7 MB) Regional quarries – southern (4.6 MB) Inglewood waste water plant (550 KB) Eltham waste water plant (520 KB)