

422430



# Hill Laboratories

A WORLD LEADER IN ANALYTICAL SERVICES

## ANALYSIS

R J Hill Laboratories Limited  
1 Clyde Street,  
Private Bag 3205  
Hamilton, New Zealand

Date Registered

Job No

**632057**

No of Samples: 0

No of Fractions: 0



**Client Name** Taranaki Regional Council 12222

**Address** Private Bag 713, STRATFORD

**Phone** 06 765 7127 **Fax** 06 765 5097

**Client Reference**

**Quote No** 32103 **Order No**

**Primary Contact** Reynolds, Shane 111952

**Submitted By**

**Charge To** Taranaki Regional Council 12222

**Results To**  Mail Primary Contact  Mail Submitter

Fax Results

Email Results

**Office use only: Job No:**

### CHAIN OF CUSTODY RECORD

**Sent to** Hill Laboratories **Date & Time:** 26/2/08  
 Please tick if you require COC to be faxed back **Name:** John Williams  
**Signature:** [Signature]

**Received at:** Hill Laboratories **Date & Time:** 26/2  
**Name:** [Signature]  
**Signature:** [Signature]

**Condition** **Temp:**  
 Room Temp  Chilled  Frozen **16.8**

Sample & Analysis details checked  
**Signature:**

**Priority**  
 Low  Normal  High  
 Urgent (ASAP, extra charge applies, please contact lab first)

**Requested Reporting Date:**

### ADDITIONAL INFORMATION

Sample Nos 1, 2 & possibly 3 are tidal river water ie salty.

### Quoted Sample Types

Soil (soil), Surface Water (sw)

| No. | Sample Name | Sample Date/Time | Sample Type | Tests Required       |
|-----|-------------|------------------|-------------|----------------------|
| 1   | 080 648     | 25/2/08 1048     | SW          | pH, metals, TPH, PAH |
| 2   | 080 649     | 1120             |             |                      |
| 3   | 080 650     | 1140             |             |                      |
| 4   | 080 651     | 1230             |             |                      |
| 5   | 080 652     | 1245             |             |                      |
| 6   | 080 653     | 1250             |             |                      |
| 7   |             |                  |             |                      |
| 8   |             |                  |             |                      |
| 9   |             |                  |             |                      |
| 10  |             |                  |             |                      |



# Hill Laboratories

A WORLD LEADER IN ANALYTICAL SERVICES

430319

**Client**  
 Name Taranaki Regional Council 12222  
 Address Private Bag 713, STRATFORD

Phone 06 765 7127 Fax 06 765 5097

Client Reference \_\_\_\_\_

Quote No 32103 Order No \_\_\_\_\_

Primary Contact Reynolds, Shane 111952

Submitted By \_\_\_\_\_

Charge To Taranaki Regional Council 12222

Results To  Mail Primary Contact  Mail Submitter

Fax Results \_\_\_\_\_

Email Results \_\_\_\_\_

**ANALYSIS**  
 R J Hill Laboratories Limited  
 1 Clyde Street,  
 Private Bag 3205  
 Hamilton, New Zealand

Date Registered 15-Mar 2008 8:34 54 am  
 Job No: **634664**  
 No. of Samples 13 No. of Fractions 74

Office use only: Job No. \_\_\_\_\_

**CHAIN OF CUSTODY RECORD**

Sent to Hill Laboratories Date & Time: 13/3/08 PM  
 Name: JOHN WILLIAMS  
 Signature: John Webb

Please tick if you require COC to be taxed back

Received at Hill Laboratories Date & Time: 13/3/08  
 Name: \_\_\_\_\_  
 Signature: Philip Horgan

Condition:  Room Temp  Chilled  Frozen 18°C

Sample & Analysis details checked \_\_\_\_\_  
 Signature: [Signature]

**ADDITIONAL INFORMATION**

\_\_\_\_\_


**Priority**  
 Low  Normal  High  
 Urgent (ASAP, extra charge applies, please contact lab first)

Requested Reporting Date: \_\_\_\_\_

**Quoted Sample Types**

Soil (Soil), Surface Water (SW)

| No. | Sample Name | Sample Date/Time | Sample Type | Tests Required                           |
|-----|-------------|------------------|-------------|--|
| 1   | 080821      | 11/3/08          | Soil        | PAH                                      |
| 2   | 080822      | ↓                | ↓           | PAH, Metals                              |
| 3   | 080823      | ↓                | ↓           | ↓  |
| 4   | 080824      | ↓                | ↓           | ↓  |
| 5   | 080825      | ↓                | ↓           | ↓  |
| 6   | 080826      | ↓                | ↓           | ↓  |
| 7   | 080827      | ↓                | ↓           | ✓ <del>PAH</del> +TPH - this sample only |
| 8   | 080828      | ↓                | ↓           | METALS (cont'd)                          |
| 9   | 080829      | ↓                | ↓           | ↓  |
| 10  | 080830      | ↓                | ↓           | ↓  |



# Hill Laboratories

A WORLD LEADER IN ANALYTICAL SERVICES

**Client**  
 Name Taranaki Regional Council 12222

Address Private Bag 713, STRATFORD

Phone 06 765 7127 Fax 06 765 5097

Client Reference \_\_\_\_\_

Quote No 32103 Order No \_\_\_\_\_

Primary Contact Reynolds, Shane 111952

Submitted By \_\_\_\_\_

Charge To Taranaki Regional Council 12222

Results To  Mail Primary Contact  Mail Submitter

Fax Results \_\_\_\_\_

Email Results \_\_\_\_\_

## ADDITIONAL INFORMATION

## ANALYSIS REQUEST

R J Hill Laboratories Limited  
 1 Clyde Street,  
 Private Bag 3205  
 Hamilton, New Zealand

Phone: + 64 (7) 858 2000  
 Fax: + 64 (7) 858 2001  
 Email: mail@hill-labs.co.nz  
 Web: www.hill-labs.co.nz

Office use only: Job No: \_\_\_\_\_

## CHAIN OF CUSTODY RECORD

Sent to Hill Laboratories Date & Time: 13/3/08 PM  
 Please tick if you require COC to be faxed back Name: JOHN WILLIAMS  
 Signature: [Signature]

Received at Hill Laboratories Date & Time: 14/3/08  
 Name: \_\_\_\_\_  
 Signature: [Signature]

Condition  Room Temp  Chilled  Frozen 18°C

Sample & Analysis details checked  
 Signature: \_\_\_\_\_

### Priority

Low  Normal  High

Urgent (ASAP, extra charge applies, please contact lab first)

Requested Reporting Date: \_\_\_\_\_

### Quoted Sample Types

Soil (Soil),  Surface Water (SW)

| No. | Sample Name | Sample Date/Time | Sample Type | Tests Required |
|-----|-------------|------------------|-------------|----------------|
| 1   | 080831      | 11/3/08          | Soil        | PAH, Metals    |
| 2   | 080832      | ↓                | ↓           | ↓ ↓            |
| 3   | 080833      | ↓                | ↓           | ↓ ↓            |
| 4   |             |                  |             |                |
| 5   |             |                  |             |                |
| 6   |             |                  |             |                |
| 7   |             |                  |             |                |
| 8   |             |                  |             |                |
| 9   |             |                  |             |                |
| 10  |             |                  |             |                |



430316

# Hill Laboratories

A WORLD LEADER IN ANALYTICAL SERVICES

**Client Name** Taranaki Regional Council 12222  
**Address** Private Bag 713, STRATFORD

**Phone** 06 765 7127 **Fax** 06 765 5097

**Client Reference**

**Quote No** 32103 **Order No**

**Primary Contact** Reynolds, Shane 111952

**Submitted By**

**Charge To** Taranaki Regional Council 12222

**Results To**  Mail Primary Contact  Mail Submitter

Fax Results

Email Results

## ANALYSIS

R J Hill Laboratories Limited  
 1 Clyde Street,  
 Private Bag 3205  
 Hamilton, New Zealand

Code Registered 15-Mar-2008 13:02:58 pm  
 Job No: **634741**  
 No of Samples 9 No of Fractions 46  
 Barcode: 031634741  
 MAA

Office use only - Chain

## CHAIN OF CUSTODY RECORD

**Sent to Hill Laboratories** **Date & Time:** 14/3/08 PM  
 Please tick if you require CDC to be faxed back  
**Name:** JIMMY WILLIAMS  
**Signature:** Jimmy Williams

**Received at Hill Laboratories** **Date & Time:** 15/3/08 9:15 AM  
**Name:** JIMMY WILLIAMS  
**Signature:** Jimmy Williams

**Condition**  
 Room Temp  Chilled  Frozen

Sample & Analysis details checked  
**Signature:**

**Priority**  
 Low  Normal  High  
 Urgent (ASAP, extra charge applies, please contact lab first)  
**Requested Reporting Date:**

## ADDITIONAL INFORMATION

**Quoted Sample Types**  
 Soil (soil), Surface Water (sw)

| No. | Sample Name | Sample Date/Time | Sample Type  | Tests Required |
|-----|-------------|------------------|--------------|----------------|
| 1   | 080949      | 13/3/08 1310     | Soil/Fill    | Metals, PAH    |
| 2   | 080950      | 1325             |              |                |
| 3   | 080951      | 1330             |              |                |
| 4   | 080952      | 1400             |              |                |
| 5   | 080953      | 1410             |              |                |
| 6   | 080954      | 1420             |              |                |
| 7   | 080955      | 1430             |              |                |
| 8   | 080861      | 12/3/08 1420     | Ground-water | Metals         |
| 9   | 080862      | " 1520           | "            | "              |
| 10  |             |                  |              |                |

437455

Job No:

Job No:

636832

**ANALYSIS**

No of Samples: 0

No of Fractions: 0

R J Hill Laboratories Limited  
1 Clyde Street,  
Private Bag 3205  
Hamilton, New Zealand



**Hill Laboratories**  
A WORLD LEADER IN ANALYTICAL SERVICES

**Client**  
Name Taranaki Regional Council 12222

Address Private Bag 713, STRATFORD

Phone 06 765 7127 Fax 06 765 5097

Client Reference

Quote No 32103 Order No 10167

Primary Contact Reynolds, Shane 111852

Submitted By JOHN WILLIAMS

Charge To Taranaki Regional Council 12222

Results To  Mail Primary Contact  Mail Submitter

Fax Results

Email Results

Office use only: Job No:

**CHAIN OF CUSTODY RECORD**

Sent to Hill Laboratories Date & Time: 1/4/08 PM

Please tick if you require COC to be faxed back  
Name: JOHN WILLIAMS  
Signature: [Signature]

Received at Hill Laboratories Date & Time: 2/4/08

Name: 11.00  
Signature: [Signature]

Condition:  Room Temp  Chilled  Frozen Temp: 14.8°C

Sample & Analysis details checked  
Signature:

Priority:  Low  Normal  High

Urgent (ASAP, extra charge applies, please contact lab first)

Requested Reporting Date:

**ADDITIONAL INFORMATION**

BTEX Not quoted.

**Quoted Sample Types**

Soil (Soil), Surface Water (SW)

| No. | Sample Name | Sample Date/Time | Sample Type | Tests Required         |
|-----|-------------|------------------|-------------|------------------------|
| 1   | 081106      | 3/3/08 1000      | Soil        | Metals, TPH, PAH, BTEX |
| 2   |             |                  |             |                        |
| 3   |             |                  |             |                        |
| 4   |             |                  |             |                        |
| 5   |             |                  |             |                        |
| 6   |             |                  |             |                        |
| 7   |             |                  |             |                        |
| 8   |             |                  |             |                        |
| 9   |             |                  |             |                        |
| 10  |             |                  |             |                        |



**Chain-of-Custody Form (Should be accompanied by a Sample Receipt Advice Form)**

From: Taranaki Regional Council Phone: 06-765-7127  
 47 Clifton Road Fax: 06-765-5097  
 Stratford

To: Capital Environmental Services  
 Phone: 04 566 3311  
 Attention: \_\_\_\_\_

Sender Legible) Shane Reynolds Laboratory Quote \$100/sample Attention: \_\_\_\_\_

PATEA FREEZING WORKS

| #                            | Sample ID | Type See Note 1 | 36798 | Test required (Use 'See Quote' if appropriate) |
|------------------------------|-----------|-----------------|-------|--|
| 1                            | Ash 1     | 0               | 36798 | Asbestos by wt or vol (approx)                 |
| 2                            | Ash 2     |                 | 36799 |  |
| 3                            | Ash 3     |                 | 36800 |  |
| 4                            | Ash 4     |                 | 36801 |  |
| 5                            | Ash 5     |                 | 36802 |  |
| 6                            | Ash 6     |                 | 36803 |  |
| 7                            | Ash 7     |                 |       |  |
| 8                            | Ash 8     |                 |       |  |
| 9                            | Ash 9     |                 |       |  |
| 10                           | Ash 10    | 36804           |       |  |
| 11                           | Ash 11    | 36805           |       |  |
| 12                           | Ash 12    | 36806           |       |  |
|                              |           | 36807           |       |  |
|                              |           | 36808           |       |  |
| Total number of samples = 12 |           |                 | 36809 |  |

RECEIVED ON  
 23 APR 2008

RECEIVED  
 22 APR 2008

ON

Notes: The information requested about the samples will make it easier for the laboratory by reducing the number of dilutions which may have to be done and allowing anticipation of matrix effects which may affect certain tests. This will help to reduce turnaround time.

1. Enter the type of sample eg. SW (surface water); GW (ground water); E (effluent); L (leachate); Sew (sewage); Soil; SI (sludge); O (other). Blanks may be identified if wishes but this is not necessary.

Received at: 22/4/08 CS Ltd on \_\_\_\_\_ by (Print) S. Helling Signed [Signature]

Survey: PATEA FREEZING WORKS (2637500 - 6159400) PATEA WORKS  
 Weather: FINE Project: ~~HUST SITE~~  
 Sampled By: SHANE Job No: 730200417 Therm ID:       
Date: 20/2/08

| Site | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |       | Comments  | Lab Sample ID (TRC) |
|------|-----------|---------------|-----------------|----------------|-------|-------|---|---------------------|
|      |           |               |                 | 2 Ltr          | Bacto | Other |   |                     |
| PFW  |           |               |                 |                |       | Bag 1 | Tallow House SE car   | 080605              |
| "    |           |               |                 |                |       | " 2   | Fellmongery u/s Mixing Room                                 | 080606              |
| "    |           |               |                 |                |       | " 3   | " outside Switch Room                                       | 080607              |
| "    |           |               |                 |                |       | " 4   | Dry Rendering SW car<br><del>Penning Floor</del> u/s SE car | 080608              |
| "    |           |               |                 |                |       | " 5   | Casings Floor u/s SW car                                    | 080609              |
| "    |           |               |                 |                |       | " 6   | Boiler House SW car   | 080610              |
| "    |           |               |                 |                |       | " 7   | Slaughter House u/s north side                              | 080611              |
|      |           |               |                 |                |       |       |   |                     |
|      |           |               |                 |                |       |       |   |                     |
|      |           |               |                 |                |       |       |   |                     |
|      |           |               |                 |                |       |       |   |                     |
|      |           |               |                 |                |       |       |   |                     |

Additional Analyses Required?: Asbestos by CES [ASB] Registration  
 Gen Comments: By:   
 Lab Use: Date: 27/2/08

Survey: PATEA FREEZING WORKS

Weather: FINE Job No: 730200417 Project: INVEST - CSITE  
 Sampled By: SHANE Date: 25/2/08 Therm.ID: F4

| Site                        | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |                    |       | Comments   | Lab Sample ID (TRC) |
|-----------------------------|-----------|---------------|-----------------|----------------|--------------------|-------|--|---------------------|
|                             |           |               |                 | D.O.           | Bacto              | Other |  |                     |
| ① Patea River Background    |           | 1048          |                 |                |                    |       | Sample from hole in d/c hose.                                | 080648              |
| ② Surface Flow from Freezer |           | 1120          |                 |                | ~0.2 l/s           |       | From trench below chimney. 2637467-6159351                   | 080649              |
| ③ Seep from Freezers        |           | 1140          |                 |                | Into modified flat |       | E end of Freezers below palm.                                | 080650              |
| ④ SE Drain                  |           | 1230          |                 |                | ~0.1 l/s           |       | 2637522 - 6159327  |                     |
| ⑤ Fellmongery Drain         |           | 1245          |                 |                | Just trickling     |       | On bank SE cor next to Norfolk / Tampesta. 2637615 - 6159210 | 080651              |
| ⑥ Bar Screen Drain          |           | 1250          |                 |                | ~0.2 l/s           |       | See Map 2637584 - 6159278                                    | 080652              |
|                             |           |               |                 |                |                    |       | See Map. 2637581 - 6159283                                   | 080653              |

Additional Analyses Required?:

Gen Comments: \_\_\_\_\_

Lab Use: \_\_\_\_\_

**RECEIVED**  
  
 25/2/08 5:09pm

By: \_\_\_\_\_ Date: 3/3/08

Registration \_\_\_\_\_ Check \_\_\_\_\_

Survey: PATEA FREEZING WORKS

Weather: FINE - OVERCAST

Job No: 730200417

Project: INVEST - C&ITE

Sampled By: SHANE


Date: 2/2/08

Therm.ID: \_\_\_\_\_

| Site                      | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |                                | Comments | Lab Sample ID (TRC) |
|---------------------------|-----------|---------------|-----------------|----------------|-------|--------------------------------|----------|---------------------|
|                           |           |               |                 | D.O.           | Bacto | Other                          |          |                     |
| ① Slaughter House N side  |           | 1405          |                 |                |       | Sample taken in SW cor of room | 080654   |                     |
| ② Paint Mix Room          |           | 1430          |                 |                |       | Sample taken in SE cor.        | 080655   |                     |
| ③ Fellmongery Switch Room |           | 1440          |                 |                |       | Composite from outside s/c     | 080656   |                     |
| ④ Tallow House            |           | 1455          |                 |                |       | SE entranceway.                | 080657   |                     |
| ⑤ Casings Floor           |           | 1505          |                 |                |       | SW cor.                        | 080658   |                     |
| ⑥ Dry Rendering           |           | 1515          |                 |                |       | SW cor.                        | 080659   |                     |
| ⑦ Boiler House            |           | 1530          |                 |                |       | SW cor                         | 080660   |                     |

Additional Analyses Required?:

Gen Comments:



By:

Date:

Registration

Check

Lab Use:

3/3/08

Survey: PATEA FREEZING WORKS

Weather: FINE

Job No: 730200417


Project: INUST - C-SITE

Sampled By: SHANE

Date: 26/2/08

Therm.ID: \_\_\_\_\_

| Site  | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers      |        |   | Comments | Lab Sample ID (TRC) |
|---|-----------|---------------|-----------------|---------------------|--------|---|----------|---------------------|
|   |           |               |                 | D.O.                | Bacto  | Other   |          |                     |
| 1 Patea River Background  |           | 0900          |                 |                     |        | From hole in d/c hose   | 080679   |                     |
| 2 SW Drain  |           | 0925          |                 |                     | ~2 L/s | 2637356-6159372   | 080680   |                     |
| 3 Stockyard Drain   |           | 0935          |                 |                     | ~3 L/s | 2637370-6159375   | 080681   |                     |
| 4 Seep from Trench  |           | 1040          |                 |                     |        | 2637441-6159335<br>Possibly flowing through destroyed drains &/or seeping from trench | 080682   |                     |
| Additional Analyses Required?: <u>pH, Metals, PAH, TPH by HULLS</u> |           |               |                 |                     |        |   |          |                     |
| Gen Comments:   |           |               |                 | By: <u>SA</u>       |        | Registration Check  |          |                     |
| Lab Use:  |           |               |                 | Date: <u>2/3/08</u> |        |   |          |                     |



Survey: LATEA FREEZING WORKS

Weather: FINE

Job No: 730200417

Project: INVEST - CSITE

Sampled By: SHANE

Date: 26/2/08

Therm ID: \_\_\_\_\_

| Site   | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |                 |       | Comments   | Lab Sample ID (TRC) |
|--|-----------|---------------|-----------------|----------------|-----------------|-------|--|---------------------|
|  |           |               |                 | D.O.           | Bacto           | Other |  |                     |
| Boiler House Reservoir                         |           | 1145          |                 |                |                 |       | Next to B/H entrance, oily sheen released when sludge sample taken | 080683              |
| Fuel Pump Shed                                 |           | 1300          |                 |                |                 |       | Sample taken from outside entranceway                              | 080684              |
| Sodium Storage                                 |           | 1310          |                 |                |                 |       | Taken from soil on conc floor                                      | 080685              |
| Paint Mix                                      |           | 1310          |                 |                |                 |       | Taken from roller door entrance<br>Grass growth in both locations  | 080686              |
|  |           |               |                 |                |                 |       |  |                     |
|  |           |               |                 |                |                 |       |  |                     |
|  |           |               |                 |                |                 |       |  |                     |
|  |           |               |                 |                |                 |       |  |                     |
| Additional Analyses Required?: <u>To Hills</u> |           |               |                 | 080683         | metals, pH, TPH |       |  |                     |
| Gen Comments:                                  |           |               |                 | 684            |                 |       |  |                     |
| Lab Use:                                       |           |               |                 |                |                 |       |  |                     |
|  |           |               |                 |                |                 |       | By: <u>SA</u>  | Registration Check  |
|  |           |               |                 |                |                 |       | Date: <u>4/3/08</u>  |                     |



Survey: PATEA FREEZING WORKS.

Weather: FINE

Job No: 730200417

Project: PATEA WORKS

Sampled By: SHANE

Date: 11/3/08

Therm ID: \_\_\_\_\_

| Site                            | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |                 | Comments | Lab Sample ID (TRC) |
|---------------------------------|-----------|---------------|-----------------|----------------|-------|-----------------|----------|---------------------|
|                                 |           |               |                 | D.O.           | Bacto | Other           |          |                     |
| Pit 1 (Sw)                      |           | 1040          |                 |                |       | 2637361-6159383 | 080821   |                     |
| Pit 4 (Sw)                      |           | 1120          |                 |                |       | 2637396-6159372 | 822      |                     |
| Pit 5 (Sw)                      |           | 1140          |                 |                |       | 2637394-6159364 | 823      |                     |
| <del>Excavation</del> Rail-line |           | 1210          |                 |                |       | 2637348-6159410 | 824      |                     |
| Pit 6 (Sw)                      |           | 1215          |                 |                |       | 2637370-6159394 | 825      |                     |
| Pit 7 (Sw)                      |           | 1225          |                 |                |       | 2637388-6159422 | 826      |                     |

Additional Analyses Required?: \_\_\_\_\_

Gen Comments: \_\_\_\_\_

Lab Use: \_\_\_\_\_

By: *MA*

Date: 11/3/08

Registration Check

Survey: PATSA FREEZING WORKS

Weather: FINE

Job No: 730200417

Project: PATEAWORKS

Sampled By: SHANE

Date: 11/3/08

Therm.ID: \_\_\_\_\_

| Site         | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |                 | Comments | Lab Sample ID (TRC) |
|--------------|-----------|---------------|-----------------|----------------|-------|-----------------|----------|---------------------|
|              |           |               |                 | D.O.           | Bacto | Other           |          |                     |
| Machine Shop |           | 1235          |                 |                |       | 2637431-6159389 | 080827   |                     |
| PIT 1 (SE)   |           | 1345          |                 |                |       | 2637624-6159206 | 828      |                     |
| PIT 2 (SE)   |           | 1410          |                 |                |       | 2637622-6157215 | 829      |                     |
| PIT 2 (SE)   |           | 1415          |                 |                |       |                 | 830      |                     |
| PIT 2 (SE)   |           | 1415          |                 |                |       |                 | 831      |                     |
| PIT 4 (SE)   |           | 1445          |                 |                |       | 2637611-6159235 | 832      |                     |

Additional Analyses Required?: \_\_\_\_\_

Gen Comments: \_\_\_\_\_

By: SA

Registration Check

Lab Use: \_\_\_\_\_

Date: 11/2/08





Survey:

PATEA FREEZING WORKS

Weather:

FINE

Sampled By:

SHANE

Job No:

730200417

Project:

SAITEA WORKS

Date:

13/3/08

Therm ID:

| Site                           | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |                   | Comments     | Lab Sample ID (TRC) |
|--------------------------------|-----------|---------------|-----------------|----------------|-------|-------------------|--------------|---------------------|
|                                |           |               |                 | D.O.           | Bacto | Other             |              |                     |
| Seal 3                         |           | 0955          |                 |                |       | 2637348 - 6159458 | 080942       |                     |
| Seal 4                         |           | 1000          |                 |                |       | 2637364 - 6159440 | 080943       |                     |
| Seal 5                         |           | 1005          |                 |                |       | 2637412 - 6159439 | 080944       |                     |
| Seal 6                         |           | 1010          |                 |                |       | 2637429 - 6159379 | 080945       |                     |
| Seal 7                         |           | 1030          |                 |                |       | 2637550 - 6159313 | 080946       |                     |
| Seal 8                         |           | 1040          |                 |                |       | 2637560 - 6159456 | 080947       |                     |
| Seal 9                         |           | 1045          |                 |                |       | 2637469 - 6159460 | 080948       |                     |
| Additional Analyses Required?: |           |               |                 |                |       |                   |              |                     |
| Gen Comments:                  |           |               |                 |                |       |                   |              |                     |
| Lab Use:                       |           |               |                 |                |       |                   |              |                     |
| By: <u>MA</u>                  |           |               |                 |                |       |                   | Registration | Check               |
| Date: <u>19/3/08</u>           |           |               |                 |                |       |                   |              |                     |







Survey: PATEA FREEZING WORKS

Weather: FINE

Job No: 730200417 Project: PATEA WORKS

Sampled By: SIHANE

Date: 21/4/08 Therm.ID: \_\_\_\_\_

| Site  | Site Code | Time (actual) | Water Temp (°C) | Bottle Numbers |       |       | Comments                               | Lab Sample ID (TRC) |
|-------|-----------|---------------|-----------------|----------------|-------|-------|--|---------------------|
|       |           |               |                 | D.O.           | Bacto | Other |  |                     |
| Ash 1 |           | 1340          |                 |                |       |       |  | 081271              |
| " 2   |           | 1343          |                 |                |       |       | Samples from burnt-out freezer section | 1272                |
| " 3   |           | 1346          |                 |                |       |       | wp's 176-187                           | 1273                |
| " 4   |           | 1349          |                 |                |       |       |  | 1274                |
| " 5   |           | 1352          |                 |                |       |       |  | 1275                |
| " 6   |           | 1400          |                 |                |       |       |  | 1276                |
| " 7   |           | 1403          |                 |                |       |       |  | 1277                |
| " 8   |           | 1406          |                 |                |       |       |  | 1278                |
| " 9   |           | 1409          |                 |                |       |       |  | 1279                |
| " 10  |           | 1412          |                 |                |       |       |  | 1280                |
| " 11  |           | 1415          |                 |                |       |       |  | 1281                |
| " 12  |           | 1418          |                 |                |       |       |  | 1282                |

Additional Analyses Required?: Asbestos - CES

Registration Check

Gen Comments:

By: AK

Lab Use:

Date:

